

AS-BUILT REPAIR QUANTITY TABLE QUANTITIES BENT 1 SPAN A FACE **ESTIMATE** ACTUAL AREA AREA VOLUME VOLUME SHOTCRETE REPAIRS SQ. FT. CU. FT. SQ. FT. CU. FT. CAP 0.0 0.0 COLUMN 0.0 0.0 VOLUME AREA AREA VOLUME CONCRETE REPAIRS SQ. FT. SQ. FT. CU. FT. CU. FT. CAP 0.0 0.0 LIN. FT. LIN. FT. EPOXY RESIN INJECTION CAP 0.0 COLUMN 0.0 SQ. FT. SQ. FT. EPOXY COATING TOP OF BENT CAP 308.0

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1" BEHIND REBAR AND MINIMUM OF 2" CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE ``TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIR AREA

CONCRETE REPAIR AREA

**EPOXY RESIN INJECTION** 

PROJECT NO. **I-5950 DAVIDSON** COUNTY 280092 BRIDGE NO. \_\_\_\_

SHEET 1 OF 2

07/25/2022 SEAL 031583 Krishna P. Sedan

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

> BENT 1 SPAN A FACE

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS						SHEET NO.
NO.	BY:	DATE:	NO.	BY:	DATE:	S1-10
1			3			TOTAL SHEETS
2			4			12