

SPAN A

AS-BUILT REPAIR QUANTITY TABLE

DECK UNDERSIDE REPAIR - SPAN A				
	ESTIMATE		ACTUAL	
SHOTCRETE REPAIR	AREA SQ. FT.	VOLUME CU. FT.	AREA SQ. FT.	VOLUME CU. FT.
UNDERSIDE OF DECK	0.0	0.0		
UNDERSIDE OF OVERHANG	0.0	0.0		
DIAPHRAGM	4.5	2.3		
OTHER REPAIRS	ESTIMATE		ACTUAL	
	I			

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1" BEHIND REBAR AND MINIMUM 2" CLEARANCE TO SAWCUT. SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

> PROJECT NO. **I-5950 DAVIDSON** _ COUNTY

BRIDGE NO. 280137

SHEET 1 OF 4

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

DECK UNDERSIDE REPAIR SPAN A

REVISIONS S2-10 DATE: DATE: BY:

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

07/25/2022

Krishna P. Seda

A. SORSENGINH

E.BAYISSA

DRAWN BY :

DATE : 3/2022

FILL FACE @ END BENT 1