

AS-BUILT REPAIR QUANTITY TABLE QUANTITIES DECK UNDERSIDE REPAIRS SPAN A ACTUAL **ESTIMATE** AREA VOLUME VOLUME AREA SHOTCRETE REPAIRS SF 0.0 UNDERSIDE OF DECK 0.0 CONCRETE DIAPHRAGM 0.0 0.0 OVERHANG 0.0 0.0 AREA VOLUME AREA VOLUME CONCRETE REPAIRS SF 0.0 UNDERSIDE OF DECK 0.0 CONCRETE DIAPHRAGM 0.0 0.0 0.0 OVERHANG 0.0 EPOXY RESIN INJECTION LIN. FT. LIN. FT. UNDERSIDE OF DECK 0.0 CONCRETE DIAPHRAGM 0.0 0.0 OVERHANG

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 2" BEHIND REBAR AND MIN. 2" CLEAR TO SAWCUT. SEE REPAIR

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

CONTRACTOR SHALL SAW CUT TO A NOMINAL DEPTH OF 1/2" BUT REINFORCING STEEL SHALL NOT BE DAMAGED.

CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAWCUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL.

SHOTCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR UNDERSIDE OF DECK REPAIRS, SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

07/25/2022

SEAL \* 031583

Krishna P. Sedan

PRIOR TO CLEANING AND PAINTING, REPLACE AND /OR TIGHTEN ANCHOR BOLT NUTS. SEE SPECIAL PROVISIONS.

> PROJECT NO. 1-5950 **DAVIDSON** \_ COUNTY BRIDGE NO. 280147

SHEET 1 OF 3

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

DECK UNDERSIDE REPAIR SPAN A

**REVISIONS** S4-06 NO. BY: DATE: DATE: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

7/25/2022 S:\DPG3\I-5950\FinalPlans\404\_011\_I5950\_SMU\_DUR\_S06\_280147.dgn ksedai