

CCTV 1207 GPS COORDINATES 35.91099 N -78.72815 W

CCTV 1207.5 GPS COORDINATES

35.91257 N -78.72814 W

INSTALL THE FOLLOWING

QUANTITY

DESCRIPTION

1


DIGITAL CCTV CAMERA

\*\* SEE NOTE 6 & 7 \*\*

I–540 EB →

## **NOTES**

- 1. REMOVE EXISTING CCTV CAMERA ASSEMBLY (CCTV 1207), EQUIPMENT CABINET, INTERCONNECT CENTER, AND WIRELESS SYSTEM.
- 2. INSTALL NEW CCTV CAMERA ASSEMBLY (CCTV 1207), EQUIPMENT CABINET, INTERCONNECT CENTER, AND WIRELESS SYSTEM ON EXISTING CCTV WOOD POLE.
- 3. RELOCATE EXISTING ETHERNET SWITCH INTO NEW EQUIPMENT CABINET.
- 4. REMOVE EXISTING CELL MODEM AT CCTV 1207 AND RETURN TO DIVISION 5 REGIONAL ITS ENGINEER (919-825-2635). RETAIN EXISTING CELL MODEM AT CCTV 1207.5.
- 5. ENSURE EXISTING FIBER OPTIC CABLE CONNECTIONS ARE LABELED BEFORE DISCONNECTING. RESPLICE OR RECONNECT FIBER OPTIC CABLE BASED ON EXISTING TERMINATION CONFIGURATION. WORK IS NOT COMPLETE UNTIL ALL FIBER OPTIC COMMUNICATIONS ARE OPERATIONAL.
- 6. CONTRACTOR SHALL MAINTAIN AND RE-USE EXISTING ELECTRICAL SERVICE AND FEEDER CONDUCTORS.
- 7. REMOVE EXISTING CCTV CAMERA (CCTV 1207.5).
- 8. INSTALL NEW CCTV CAMERA (CCTV 1207.5) ON EXISTING CCTV WOOD POLE.




← I-540 WB

(CCTV 1207.5)

LEESVILLE

RD.



MM 7

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

ITS DEVICE REPLACEMENT

DIVISION 05 WAKE CO.

PLAN DATE: AUGUST 2021 REVIEWED BY: A.J.\_SKUCE,\_PE\_
529 PREPARED BY: J. WALDEN REVIEWED BY:

REVISIONS INIT. DATE

