
AS-BUILT REPAIR QUANTITY TABLE SUPERSTRUCTURE REPAIRS

	SPAN 7		SPAN 8		SPAN 9	
	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL	ESTIMATE	ACTUAL
CLEANING & PAINTING EXISTING BEARINGS WITH HRSCA	5 EA		EA		EA	

* FOR QUANTITIES FOR BEARING REPAIRS, SEE BEARING REPAIR SHEET.



+

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE TABLE ABOVE.

FOR CLEANING & PAINTING EXISTING BEARINGS WITH HRSCA, SEE SPECIAL PROVISIONS.

FOR BEARING REPAIRS, SEE "BEARING REPAIRS" SHEET.


FOR ZONE PAINTING OF EXISTING STRUCTURE, SEE SPECIAL PROVISIONS.

FOR DETAILS OF CLEANING AND PAINTING GIRDER ENDS (CPG), SEE "MISCELLANEOUS REPAIRS" SHEET.

DRAWN BY :	ALLEN J. MCSWAIN	DATE : _01/2022_
CHECKED BY :	JACOB H.DUKE	DATE : <u>01/2022</u>
DESIGN ENGINEER	OF RECORD:A.AGUIRRE	DATE : <u>01/2022</u>

4/21/2022 I5915B_SMU_SSR03_480006.dgn daguirre

LEGEND:



BR

* BEARING REPAIRS

PARTIAL PLAN



