

A A	LEGEND		
В В Ц С		CONCRETE REPAIR AREA (CR)	
		SHOTCRETE REPAIR AREA (SCR)	SHC
		EPOXY RESIN INJECTION (ERI)	
3.4 SF SCR			CON
WEST AND			1

BOTTOM FACES

SOUTHWEST CORNER

-6.0 LF ERI

-4.1 SF SCR Northeast corner

> DOCUMENT NOT CO FINAL UNLESS SIGNATURES COM

AS-BUILT REPAIR QUANTITY TABLE QUANTITIES ACTUAL ESTIMATE AREA SQ.FT VOLUME CU.FT. AREA SQ.FT VOLUME CU.FT. HOTCRETE REPAIRS CAP/BACKWALL 14.5 5.0 COLUMN/PILE 2.8 6.4 AREA SQ.F⁻⁻ VOLUME AREA SQ.FT VOLUME CU.FT. ONCRETE REPAIRS CU. F CAP _ _ EPOXY RESIN INJECTION LIN.FT. LIN.FT. CAP/BACKWALL _ 10.0 COLUMN/PILE

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS" SHEETS.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE TABLE ABOVE.

CRACKING LOCATIONS AND QUANTITIES FOR LOCATIONS DESCRIBED AS ``SCATTERED THROUGHOUT'' IN THE INSPECTION REPORT ARE BASED ON THE BEST INFORMATION AVAILABLE. THE ENGINEER AND CONTRACTOR SHALL IDENTIFY AND REPAIR ALL CRACKS >=1/16" AS DESCRIBED IN THE SPECIAL PROVISIONS AT EACH BENT.

AVERAGE CONCRETE COVER IS EXPECTED TO BE FROM 2"TO 3" ON THE CAP AND FROM $1^{1}/_{2}$ "TO 2" ON THE PILES. ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING EXCAVATION/ DEMOLITION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE "CONCRETE RESTORATION DETAILS" SHEETS.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

REPAIRS TO THE BENT CAP MAY REQUIRE BRIDGE JACKING.FOR BRIDGE JACKING, SEE SPECIAL PROVISIONS.

	PROJECT NO. <u>I-5915B</u> <u>IREDELL</u> COUNTY BRIDGE NO. <u>480066</u> Sheet 3 of 4
DocuSigned by SEAL Dic A Lawing 4/29/2022 Dic A AGUINT	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SUBSTRUCTURE REPAIRS
KCA	BENT 2
KISINGER CAMPO	REVISIONS SHEET NO.
& ASSOCIATESONSIDEREDSALLMPLETEDRALENC FIRM LICENSE: C-1506	NO. BY: DATE: NO. BY: DATE: S10-10 1 3 3 TOTAL SHEETS 12