

LEGEND	
CONCRETE REPAIR AREA (CR)	
SHOTCRETE REPAIR AREA (SCR)	SH
EPOXY RESIN INJECTION (ERI)	

FINAL UNLE SIGNATURES C	DOCUMENT	NOT	
SIGNATURES C	FINAL	UNL	F
	SIGNATU	res	С

AS-BUILT REPAIR QUANTITY TABLE						
	QUANTITIES					
	ESTIMATE		ACTUAL			
HOTCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
CAP/BACKWALL	2.8	1.0				
COLUMN/PILE	_	_				
ONCRETE REPAIRS	AREA SQ.FT.	VOLUME CU.FT.	AREA SQ.FT.	VOLUME CU.FT.		
САР	_	_				
POXY RESIN INJECTION	LIN.FT. LIN.FT.		,FT.			
CAP/BACKWALL	-	_				
COLUMN/PILE	-	-				

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE.MINIMUM OF 1"BEHIND REBAR AND MINIMUM 2"CLEARANCE TO SAWCUT.FOR REPAIR DETAILS, SEE "CONCRETE RESTORATION DETAILS" SHEETS.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE.IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE TABLE ABOVE.

CRACKING LOCATIONS AND QUANTITIES FOR LOCATIONS DESCRIBED AS "SCATTERED THROUGHOUT" IN THE INSPECTION REPORT ARE BASED ON THE BEST INFORMATION AVAILABLE. THE ENGINEER AND CONTRACTOR SHALL IDENTIFY AND REPAIR ALL CRACKS >=1/16" AS DESCRIBED IN THE SPECIAL PROVISIONS AT EACH BENT.

AVERAGE CONCRETE COVER IS EXPECTED TO BE FROM 2"TO 3"ON THE CAP AND FROM  $1\frac{1}{2}$ "TO 2"ON THE PILES.ACTUAL CONCRETE COVER SHALL BE DETERMINED BY THE CONTRACTOR AND PRESENTED TO THE ENGINEER PRIOR TO BEGINNING EXCAVATION/ DEMOLITION.

FOR CONCRETE AND SHOTCRETE REPAIRS, SEE "CONCRETE RESTORATION DETAILS" SHEETS.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

REPAIRS TO THE BENT CAP MAY REQUIRE BRIDGE JACKING.FOR BRIDGE JACKING, SEE SPECIAL PROVISIONS.

		PROJECT NO. <u>I-5915</u> <u>IREDELL</u> CO BRIDGE NO. <u>480096</u> Sheet 1 of 3	UNTY
DocuSigned b Dic to d d 47297/20223	SEAL I	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTA RALEIGH SUBSTRUCTURE REPAIRS	TION
	KCA	END BENTS 1 & 2	
	KISINGER CAMPO	REVISIONS	SHEET NO.
CONSIDERED SS ALL OMPLETED	301 FAYETTEVILLE ST., SUITE 1500 RALEIGH, NC 27601 (919) 882-7839 NC FIRM LICENSE: C-1506	NO. BY: DATE: NO. BY: DATE:   1 3 4	S13-7 TOTAL SHEETS 9