

01  $\infty$ 

S


100%

0


 $\circ$ 01

Ū

 $+ ^{40}$  $\circ$ 







NOTES:				
REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE.IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.				
FOR REPAIRS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET.				
FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.				
FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.				
SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.				
CONTRACTOR SHALL SAW CUT TO A MINIMUM DEPTH OF $1/2$ "BUT REINFORCING STEEL SHALL NOT BE DAMAGED.CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAW CUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL.				
CONTRACTOR SHALL SAW CUT THE REPAIR AREAS SO THAT THE CORNERS ARE SQUARE AS INDICATED ON THE DETAILS.				
APPLY EPOXY PROTECTIVE COATING TO ALL SIDES OF THE CONCRETE PILES. EPOXY COATING SHALL BE APPLIED 4 FEET UP THE PILES FROM THE GROUND LINE.FOR EPOXY COATING, SEE SPECIAL PROVISIONS.				
FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.				
WHEN COLUMN REPAIRS ARE INDICATED TO GROUND LINE,EXTEND REPAIR ONE (1)FOOT MIN.BELOW GROUND LINE.				
SHOTCRETE REPAIR				
CONCRETE REPAIR (FORM & POUR)				
ERI - EPOXY RESIN INJECTION				

	PROJECT NO GUILFO BRIDGE NO			
SHEET 2 OF 2				
RTH CAROLINE	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH			
DocuSigned by: John Yannaccone 032492 781361754678456. 11/17/2022		BENT 1 An b Side		
	REVISIONS		SHEET NO.	
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED	NO. BY: DATE: NO 1 33 2 4	3	S8-8 total sheets 127	