### STATE OF NORTH CAROLINA DIVISION OF HIGHWAYS

N.C.		15BPR.59	<b>1A</b>
STAT	E PROJ. NO.	P. A. PROJ. NO.	DESCRIP
15	BPR.59		P.E
15	BPR.59	_	CON
	•		

STATE PROJECT REFERENCE NO.

## DURHAM & WAKE COUNTIES


LOCATION: BRIDGE #310306 ON SR 1118 (FAYETTEVILLE RD.) OVER I-40


BRIDGE #911039 ON SR 2517 (ROGERS LN.) OVER I-87/US64/US264, CRABTREE CREEK AND NS RAILROAD

BRIDGE #911083 ON NC-98 OVER US-1 (CAPITAL BLVD.)
BRIDGE #911084 ON NC-98 OVER RICHLAND CREEK

# INDEX OF STRUCTURES SHEETS

SHEET No.	<b>DESCRIPTION</b>	SHEET No.	<b>DESCRIPTION</b>	SHEET No.	<b>DESCRIPTION</b>
1	TITLE SHEET	<i>\$2-06</i>	EXPANSION JOINT SEAL REPAIR SHEET 1	STRUCTURE	E. No. 911084
<i>1A</i>	INDEX OF SHEETS	<i>S2–07</i>	EXPANSION JOINT SEAL REPAIR SHEET 2	S4-01	GENERAL DRAWING
S-01	LOCATION SKETCHES	<i>\$2–08</i>	MODULAR EXPANSION JOINT REPAIR	<i>S4–02</i>	TYPICAL SECTION
<i>S–02</i>	TOTAL BILL OF MATERIALS	<i>\$2-09</i>	3 BAR METAL RAIL REPAIR SHEET 1	<b>S4–0</b> 3	DECK SURFACE REPAIR - SPAN A
STRUCTURE	E No. 310306	<i>S2–10</i>	3 BAR METAL RAIL REPAIR SHEET 2	<i>S4</i> – <i>04</i>	DECK SURFACE REPAIR - SPAN B
<i>S1–01</i>	GENERAL DRAWING	S2-11	3 BAR METAL RAIL REPAIR SHEET 3	<b>S4–0</b> 5	DECK SURFACE REPAIR - SPAN C
<i>S1–02</i>	TYPICAL SECTION	S2–12	DECK UNDERSIDE REPAIR – SPAN A	<i>S4</i> – <i>06</i>	DECK SURFACE REPAIR - SPAN D
<i>S1–03</i>	DECK SURFACE REPAIR - SPAN A	S2-13	DECK UNDERSIDE REPAIR - SPAN B	<i>S4</i> – <i>07</i>	FOAM JOINT REPAIR
<i>S1–04</i>	DECK SURFACE REPAIR – SPAN B	<i>S2–14</i>	DECK UNDERSIDE REPAIR - SPAN C	<b>S4–0</b> 8	DECK UNDERSIDE REPAIR – SPAN A
<i>S1–05</i>	FOAM JOINT REPAIR	S2-15	END BENT 1	<i>S4</i> – <i>09</i>	DECK UNDERSIDE REPAIR – SPAN B
<i>S1–06</i>	EXPANSION JOINT SEAL REPAIR	S2-16	BENT 1	S4-10	DECK UNDERSIDE REPAIR – SPAN C
<i>S1–07</i>	EXPANSION JOINT SEAL REPAIR SHEET 2	<i>S2–17</i>	BENT 2	S4-11	DECK UNDERSIDE REPAIR – SPAN D
<i>S1–08</i>	EXPANSION JOINT SEAL REPAIR SHEET 3	S2–18	END BENT 2	<b>S4–12</b>	END BENT 1
<i>S1–09</i>	CONCRETE BARRIER RAIL REPAIR	STRUCTURI	E No. 911083	<b>S4–13</b>	BENT 1 – SPAN A FACE
<i>S1–10</i>	DECK UNDERSIDE REPAIR	S3-01	GENERAL DRAWING	S4-14	BENT 1 – SPAN B FACE
<i>S1–11</i>	END BENT 1	<b>S</b> 3-02	TYPICAL SECTION	<b>S4–15</b>	BENT 2 – SPAN B FACE
<b>S1–1</b> 2	BENT 1 – SPAN A FACE	<b>S</b> 3-03	DECK SURFACE REPAIR - SPAN A	S4-16	BENT 2 – SPAN C FACE
<b>S1–1</b> 3	BENT 1 – SPAN B FACE	<i>S3–04</i>	DECK SURFACE REPAIR - SPAN B	<i>S4–17</i>	BENT 3 – SPAN C FACE
<i>S1–14</i>	END BENT 2	<b>S</b> 3-05	FOAM JOINT REPAIR	S4–18	BENT 3 – SPAN D FACE
<b>S1–1</b> 5	INCIDENTAL MILLING	<b>S</b> 3-06	CONCRETE BARRIER RAIL REPAIR	S4-19	END BENT 2
STRUCTURE	E No. 911039	<i>\$3-07</i>	DECK UNDERSIDE REPAIR	<i>S4–20</i>	SLOPE PROTECTION REPAIR
S2-01	GENERAL DRAWING	<b>S</b> 3-08	END BENT 1	<b>S4–21</b>	INCIDENTAL MILLING
<b>S</b> 2-02	TYPICAL SECTION	<b>S</b> 3-09	BENT 1 – SPAN A FACE	<b>STANDARD</b>	SHEETS
<b>S</b> 2-03	DECK SURFACE REPAIR – SPAN A	<b>S</b> 3–10	BENT 1 - SPAN B FACE	<b>S-0</b> 3	CAP AND COLUMN REPAIR DETAILS
<i>S2-04</i>	DECK SURFACE REPAIR – SPAN B	S3-11	END BENT 2	<i>S–04</i>	PRESTRESSED GIRDER REPAIR DETAILS
<b>S</b> 2-05	DECK SURFACE REPAIR – SPAN C	<b>S</b> 3–12	INCIDENTAL MILLING	SN	STANDARD NOTES





#### TYPE OF WORK:

BRIDGE PRESERVATION – MILLING AND REPAVING APPROACH ROADWAYS, DIAMOND GRINDING APPROACH SLAB, SHOTBLASTING AND SILANE DECK TREATMENT, FOAM JOINT REPLACEMENT, EXPANSION JOINT GLAND REPLACEMENT, MODULAR EXPANSION JOINT GLAND REPLACEMENT, SHOTBLASTING AND SILANE BARRIER RAIL TREATMENT, SAW CUTTING OF BARRIER RAIL, 3-BAR METAL RAIL SECTION REPLACEMENTS, CONCRETE MEDIAN ISLAND REPAIR, CLEANING AND PAINTING EXISTING STRUCTURE, CLEANING AND PAINTING EXISTING STEEL, CLEANING AND EPOXY COATING PRESTRESSED GIRDER ENDS, SHOTCRETE REPAIRS, CLEANING AND EPOXY COATING SUBSTRUCTURE CAPS, SLOPE PROTECTION VOID FILLING AND REPAIR.

Prepared in the Office of:

#### **DIVISION OF HIGHWAYS**

STRUCTURES MANAGEMENT UNIT
1000 BIRCH RIDGE DR.
RALEIGH, N.C. 27610