

SUBSTRUCTURE REPAIR QUANTITY TABLE

		•			
DENT 1	QUANTITIES				
BENT 1	ESTIMATE		ACTUAL		
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF	
CAP	0	0			
COLUMN	0	0			
CONCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF	
CAP	0	0			
COLUMN	0	0			
EPOXY RESIN INJECTION		LINEAR FT		LINEAR FT	
CAP		0			
COLUMN		0			
EPOXY COATING		AREA SF		AREA SF	
CAP		529.3			
-					

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 2" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE REPAIR QUANTITY TABLE.

CLEAN AND REMOVE DEBRIS FROM THE TOP OF THE CAP AND APPLY EPOXY PROTECTIVE COATING. EPOXY COATING SHALL BE APPLIED TO THE TOP SURFACE OF THE CAP. THE CONTRACTOR SHALL NOT COAT THE AREA OF THE CAP BENEATH THE MASONRY PLATES. FOR EPOXY COATING, SEE SPECIAL PROVISIONS.

CONCRETE REPAIRS MAYBE SUBSTITUTED IN LIEU OF SHOTCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

SHOTCRETE REPAIR AREA



CONCRETE REPAIR AREA



EPOXY RESIN INJECTION

PROJECT NO. 15BPR.59

WAKE COUNTY

BRIDGE NO. 911083

SHEET 1 OF 2



STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION
RALEIGH

SUBSTRUCTURE REPAIRS

BENT 1 SPAN A FACE

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS					SHEET NO.	
NO.	BY:	DATE:	NO.	BY:	DATE:	S3-09
1			3			TOTAL SHEETS
2			4			12