



ELEVATION

END BENT 2

SHOTCRETE REPAIR

CONCRETE REPAIR (FORM & POUR)

ERI - EPOXY RESIN INJECTION

NOTES: REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUALITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE.

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MINIMUM OF 1"BEHIND REBAR AND MINIMUM OF 2"

CLEARANCE TO SAWCUT. FOR REPAIR DETAILS, SEE "TYPICAL CAP REPAIR

AS-BUILT REPAIR QUANTITY TABLE

AREA

2.5

0.0

3.5

ESTIMATE

END BENT 1 REPAIRS

SHOTCRETE REPAIRS

CONCRETE REPAIRS

EPOXY COATING

END BENT 2 REPAIRS

SHOTCRETE REPAIRS

CONCRETE REPAIRS

EPOXY COATING

TOP OF BENT CAP

DETAILS" SHEET.

EPOXY RESIN INJECTION

TOP OF BENT CAP

EPOXY RESIN INJECTION

CAP

CAP

CAP

CAP

BACKWALL

BACKWALL

BACKWALL

BACKWALL

QUANTITIES

VOLUME

CF

1.3

0.0

1.8

LENGTH

0.0

5.5

SQ. FT

105

VOLUME

CF

0.0

0.0

0.0

LENGTH

0.0

0.0

SQ. FT

ESTIMATE

AREA SF

0.0

0.0

0.0

QUANTITIES

ACTUAL

AREA DEPTH VOLUME SF FT CF

LENGTH

LF

SQ. FT

ACTUAL

AREA DEPTH VOLUME SF FT CF

LENGTH

SQ. FT

CONTRACTOR SHALL SAW CUT TO A MINIMUM DEPTH OF 1/2" BUT REINFORCING STEEL SHALL NOT BE DAMAGED

CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAW CUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL.

CONTRACTOR SHALL SAW CUT THE REPAIR AREAS SO THAT THE CORNERS ARE SQUARE AS INDICATED ON THE DETAILS.

FOR CONCRETE REPAIRS, SEE SPECIAL PROVISIONS.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR EPOXY RESIN INJECTION, SEE SPECIAL PROVISIONS.

PROJECT NO. I-5889B BUNCOMBE \_ COUNTY 100339 BRIDGE NO. \_\_\_



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

S2-8

DATE:

END BENT 1 & 2

GANNETT FLEMING

One Glenwood Avenue	DOCUM
Suite 900 Raleigh, NC 27603	F.
919-420-7660 VC 110 No. E-0270	SIGN

	REVISION				
CUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	
FINAL UNLESS ALL SIGNATURES COMPLETED	1			<b>₩</b>	
0 1 0 1 W 1 0 1 (2 0 0 0 W) 2 2 1 2 3	2			4	

\_ DATE : <u>6/2022</u> J. MYA DRAWN BY \_ DATE : <u>6/2022</u> J. YANNACCONE CHECKED BY : \_\_\_

NO REPAIRS NOTED FOR END BENT 2 DURING FIELD SCOPING. THE CONTRACTOR AND ENGINEER SHALL INSPECT END BENT 2 PRIOR TO BEGINNING WORK.