

NICHOLAS J. TENNYSON Secretary

August 12, 2016

MEMORANDUM TO: William T. Goodwin, PE

Project Development-Bridge Section - Section Head

Project Development and Environmental Analysis Branch

ATTN: John Williams

Project Development Engineer

- DocuSigned by:

8/12/2016

FROM: Gordon Box, LG

GeoEnvironmental Project Manager

GeoEnvironmental Section Geotechnical Engineering Unit

TIP NO: B-5808
WBS: 45762.1.1
COUNTY: Cabarrus
DIVISION 10

DESCRIPTION: Replace Bridge No. 57 & 59 on US 29 & US 601 over Irish Buffalo Creek

SUBJECT: GeoEnvironmental Report for Planning

The GeoEnvironmental Section has completed the GeoEnvironmental Report for Planning. This report has the following components and is transmitted as:

X Hazardous Materials Report (13) pages

Please contact me if you have any questions concerning this project.

Hazardous Materials Report

The GeoEnvironmental Section of the Geotechnical Engineering Unit has investigated the above referenced project to identify hazardous material sites for inclusion in the environmental document.

HAZARDOUS MATERIALS EVALUATION

Purpose

This section presents the results of a hazardous material evaluation conducted along the above referenced project. The main purpose of this investigation is to identify properties within the project study area that are or may be contaminated and therefore result in increased project costs and future liability if acquired by the Department. Hazardous material impacts may include, but are not limited to, active and abandoned underground storage tank (UST) sites, hazardous waste sites, regulated landfills and unregulated dumpsites.

Techniques/Methodologies

The Geographical Information System (GIS) was consulted to identify known sites of concern in relation to the project corridor. GeoEnvironmental Section staff conducted a field reconnaissance along the Replace Bridge No. 57 & 59 on US 29 & US 601 over Irish Buffalo Creek on May 16, 2016. A search of appropriate environmental agencies' databases was performed to assist in evaluating sites identified during this study.

Findings

UST Facilities

Nine petroleum sites were identified within the project limits.

Hazardous Waste Sites

No Hazardous Waste Sites were identified within the project limits.

Landfills

No apparent landfills were identified within the project limits.

Other GeoEnvironmental Concerns

No other geoenvironmental concerns were identified within the project limits.

Anticipated Impacts

The GeoEnvironmental Section observed nine potentially contaminated UST properties during the field reconnaissance and regulatory agencies' records search (see the following table and appendices for details).

Historical Automotive Service and/or Automotive Recycling 570 – 530 Concord Pkwy N Concord, NC

Facility ID #: NA Incident #: NA

Property Owner

Whitaker Investments LLC A NC LLC 530 Concord Pkwy N Concord, NC

UST Owner: NA



First Image c. 2015; second image NCDOT Historical Aerial 2/1/1961 Mission 129, exposure 13 (top of page is northward); Third Image Google Streetview c. 2016 (view northeastward)

This parcel is located south of the intersection of US 29 & US 601 and Poplar Tent Rd. This single parcel contains Dan'elle Clothing Warehouse, Punchy's Diner, and Punchy Whitaker's Wheel and Tire Pros. This parcel does not appear on the UST Section Registry nor are any NCDEQ incidents associated. There is no evidence of USTs or UST removals. Hydraulic lifts were not observed at the modern Punchy Whitakers Wheel and Tire Pros. In a NCDOT Historical Aerial, several cars and pre-existing buildings were observed that suggest that auto service and/or auto recycling was performed, thus hydraulic lifts or spills from auto recycling may be present. This site is anticipated to present low geoenvironmental impacts to the project.

> Premier Auto Sound Security Concord Ink Tattoo/Piercing 590 Concord Pkwy N Concord, NC

Property Owner

Whitaker Donald E 3661 Richwood Cir. Kannapolis, NC

UST Owner: NA

Facility ID #: NA

Incident #: NA



First Image Streetview c. 2015 view eastward Image c. 2015; Second image NCDOT Historical Aerial 2/1/1961 Mission 129, exposure 13 (top of page is northward)

This apparent former gas station is located on southeastern quadrant of the intersection of US 29 & US 601 and Poplar Tent Rd. The architectural style, age, location and NCDOT Historical Aerial suggest that it operated as a gas station c. 1961. This site is anticipated to present low geoenvironmental impacts to the project.

Citgo AKA Carolina Quick Lube 589 Concord Pkwy N Concord, NC

Facility ID #: 0-034794

Incident #: NA

Property Owner

United Oil of the Carolinas PO Box 68 Gastonia, NC

UST Owner: United Oil of the Carolinas

PO Box 68

2758 E Ozark Ave. Gastonia, NC



View southeastward (Google Streetview c. 2015)

This active gas station is located on south-southwestern quadrant of the intersection of US 29 & US 601 and Poplar Tent Rd. A groundwater monitoring well was observed near the store building. **This site is anticipated to present low geoenvironmental impacts to the project.**

Marathon Mid-State Oil Company/ Sun Oil 603 Concord Pkwy Concord, NC

Facility ID #: 00-0-0000032782

(USTNum: MO-3470) **Incident #:** 8727 (c. 1992)

Property Owner

Prime Business LLC A NC Manager Maged LLC 1534 Copperplate Rd. Charlotte, NC

UST Owner: Mid-State Oil Co.

Richard King

PO Box 849Lexington, NC AKA

Prime Business LLC A NC

Manager Maged LLC 1534 Copperplate Rd.

Charlotte, NC



View northwestward (Google Streetview c. 2015)

This active gas station is located on the western quadrant of the intersection of US 29 & US 601 and Poplar Tent Rd. An Incident was assigned by NCDEQ. This site is anticipated to present low geoenvironmental impacts to the project.

Your Custom Car AKA Twice the Ice AKA Security Oil Company 2242 Poplar Tent Rd. Kannapolis, NC

Facility ID #: 00-0-000000147

(USTNum: MO-5470) **Incident #:** 19034 (c. 1998)

Property Owner

Security Oil Co., Inc. PO Box 5028 Concord, NC

UST Owner: Security Oil Co., Inc.

Grady Carpenter 2242 Poplar Tent Rd. Concord, NC



First image view northwestward; Second Image NCDOT Historical Aerial 3/10/1993 Mission 3092, exposure 60 (top of page is northward);

This former gas station and/or oil company facility is located approximately 300 feet west of the intersection of US 29 & US 601 and Poplar Tent Rd. According to the UST Section Registry USTs were registered and an Incident recorded. Four USTs are evident west of the building. **This site is anticipated to present low geoenvironmental impacts to the project.**

Cement Plant 470 McGill Ave. PO Box 508 Concord, NC

Facility ID #: 003384, 028860

Incident #: NA

Property Owner

Concrete Supply Co., LLC

A NC LLC PO Box 5247 Charlotte, NC

UST Owner: Carolina Oil Co of Concord, Inc.

PO Box 5010 Concord, NC

AKA

Concrete Supply Co. 3823 Raleigh St. Charlotte, NC



View northward (Google Streetview c. 2015)

This cement plant is located on northeastern quadrant of the intersection of US 29 & US 601 and Poplar Tent Rd. According to the UST Section Registry two USTs were reportedly filled in situ with inert material. An above ground storage tank (AST) is currently on site currently (blue circle). **This site is anticipated to present low geoenvironmental impacts to the project.**

Webster Radiator and A/C 650 Concord Pkwy N. Concord, NC

Facility ID #: NA Incident #: NA

Property Owner

Greenwich Investors XLV Reo LLC c/o Wmd Asset Management LLC 6279 Dupont Station Ct. E Jacksonville, FL UST Owner: NA



View north-northeastward (Google Streetview c. 2015)

This former location of Webster Radiator and A/C is located 1000 feet north of the intersection of US 29 & US 601 and Poplar Tent Rd. Hydraulic lifts may be present behind the bay five bay doors. **This site is anticipated to present low geoenvironmental impacts to the project.**

Cabarrus Schools Maintenance Facility 660 Hwy 29 N Concord, NC

Facility ID #: 00-0-000028999 (UST

Num MO-5188) **Incident #:** 17721 (c. 1996)

Property OwnerCabarrus County

PO Box 707 Concord, NC

UST Owner: Cabarrus County Schools

PO Box 388 Concord, NC



View north-northeastward (Google Streetview c. 2015)

This school maintenance facility is located 1000 feet north of the intersection of US 29 & US 601 and Poplar Tent Rd. behind the site of Webster Radiator and A/C. According to the UST Section Registry a UST registered and an Incident recorded, and a No Further Action status was reportedly granted c. 2001. **This site is anticipated to present low geoenvironmental impacts to the project.**

9) **Property Name** Car Battery Sales

688 Concord Pkwy N Concord, NC

Facility ID #: NA Incident #: NA **Property Owner**

Frances Medlin Fam. Farms I LLC PO Box 703 Concord, NC

UST Owner: NA



First Image NCDOT Historical Aerial 3/10/1993 Mission 3092, exposure 60 (top of page is northward); Second Image view northward

This car battery sales facility and apparent former gas station is located 1000 feet north of the intersection of US 29 & US 601 and Poplar Tent Rd. A NCDOT Historical Aerial suggests it was a gas station (first image, blue circle), and an apparent former pump island is evident in the concrete (second image, blue circle). **This site is anticipated to present low geoenvironmental impacts to the project.**

Please note that discovery of additional sites not recorded by regulatory agencies and not reasonably discernible during the project reconnaissance may occur. The GeoEnvironmental Section should be notified immediately after discovery of such sites so their potential impact(s) may be assessed.

If there are questions regarding the geoenvironmental issues, please contact me, at 919-707-6859.

8/12/2016

GeoEnvironmental Project Manager

GeoEnvironmental Section
Geotechnical Engineering Unit

Gordon Box, LG

Cc:

John Pilipchuk, LG, PE, State Geotechnical Engineer

David Chang, Ph.D., PE, State Hydraulics Engineer

Charles Brown, PE, PLS, State Locations and Surveys Engineer

Tom Koch, PE, Assistant State Structures Engineer

Randy Bowers, Division Design Construction Engineer

Brian Skeens, PE, Area Roadway Construction Engineer

Kenneth Hill, Division Right of Way Agent

Eric Williams, PE, Geotechnical Regional Manager

Shane Clark, Geotechnical Regional Manager

Roger Worthington, PE, State Utilities Engineer, Utilities Unit


Teresa Hart, PE, CPM, Support Services Section Head, Project Development

Jody Kuhne, LG, PE, Regional Geological Engineer

NCDOT Service Account, Roadway Design

Row-notify@ncdot.gov

File



TIP: B-5808 **Project # 45762.1.1**

Bridge Photographs

5/16/16



Bridge 57 on US 29 & US 601 over Irish Buffalo Creek. View to the north.



Bridges 57 (left) & 59 (right) on US 29 & US 601 over Irish Buffalo Creek. View to the south. (Google Streetview c. 2015)



Bridge 57 on US 29 & US 601 view of Irish Buffalo Creek northwestward. (Google Streetview c. 2015)

Bridge 59 on US 29 & US 601 view of Irish Buffalo Creek southeastward. (Google Streetview c. 2015)