

Strain Pole Attachments


NOTE:

- 1. Strap all signal cables to the side of the pole with $\sqrt[3]{4}''$ stainless steel straps when the distance between the spanwire attachment clamp and the weatherheads exceeds 3'-0''.
- 2. Provide minimum two spanwire pole clamps per pole.
- 3. It is prohibited to attach two span wires at one pole clamp.
- 4. For general requirements refer to NCDOT Standard Specifications for Roadway and Structures, January 2018.


PROJECT ID. NO. SHEET NO. SIG.M6

#0#


Stra



Attachment of Cable to Intermediate Metal Pole



Metal Pole Grounding Detail For Strain Pole and Mast Arm



S:*IIS&SU*IIS SIGNAIS*SIGNAI DESIGN SECTION*EASTEFN REGION*M SNEETS*ZUIO*ZU14 SIG.M6 STA. FADFICATION DETAINS-STRA rnzinser