ANCHOR UNIT REPAIR DETAIL

TIGHTEN BOTTOM CONNECTION MARKED IN THE PHOTO

REPLACE BOLT AS NEEDED WITH AN ADHESIVELY ANCHORED BOLT. FOR ADHESIVELY ANCHORED BOLTS AND DOWELS, SEE SECTION 420-13 OF THE STANDARD SPECIFICATIONS.

PAYMENT FOR TIGHTENING OR REPLACEMENT SHALL BE INCIDENTAL TO THE VARIOUS PAY ITEMS FOR THIS PROJECT.

I-6039 PROJECT NO._

NEW HANOVER COUNTY

640044

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

APPROACH ROADWAY ASPHALT MILLING AND GUARDRAIL

JECT.		& ASSOCIATES	REVISIONS						SHEET NO.
			NO.	BY:	DATE:	NO.	BY:	DATE:	S1-9
	DOCUMENT NOT CONSIDERED FINAL	L 301 FAYETTEVILLE ST., SUITE 1500 RALEIGH, NC 27601 (919) 882-7839	1			3			TOTAL SHEETS
	UNLESS ALL SIGNATURES COMPLETED	NC FIRM LICENSE: C-1506	2			4			13

DRAWN BY: JASON M. DEBONE
CHECKED BY: ALLEN J. MCSWAIN
DESIGN ENGINEER OF RECORD: JACOB H. DUKE

DATE: 01/2023
DATE: 01/2023
DATE: 01/2023

4/17/2023 640044_I6039_SMU_AR01.dgn jduke