

TYPE A RETAINER RING(RR)


(14 ASSEMBLIES REQUIRED) (7 - BENT 1) (7 - BENT 2)

NOTES:

- STRUCTURAL STEEL SHALL BE AASHTO M270 GRADE 36 OR HIGHER.
- 2. ALL STRUCTURAL STEEL SHALL, ANCHOR BOLTS, NUTS ADN WASHERS SHALL BE GALVANIZED IN ACCORDANCE WITH THE STANDARD SPECIFICATIONS.
- 3. ADHESIVELY ANCHORED BOLTS SHALL CONFORM TO THE STANDARD SPECIFICATIONS. WITH THE EXCEPTION OF FIELD TESTING, FIELD TESTING OF THE ADHESIVELY ANCHORED BOLTS IS NOT REQUIRED.
- THE STRUCTURAL STEEL FABRICATOR SHALL PROVIDE SHOP DRAWINGS TO THE ENGINEER FOR REVIEW AND APPROVAL.
- ANCHOR BOLTS SHALL BE SHIFTED AS NECESSARY TO CLEAR EXISTING REINFORCING STEEL.
- INSTALLATION OF ADHESIVELY ANCHORED BOLTS SHALL BE INCLUDED IN THE LUMP SUM PRICE EITHER "RETAINER RING" OR "EXPANSION BEARING REPAIR"
- FOR KEEPER ASSEMBLY LOCATIONS, SEE "SUPERSTRUCTURE REPAIRS" SHEETS.

_ DATE : 01/2023 JASON M. DEBONE CHECKED BY: ALLEN J. MCSWAIN
DESIGN ENGINEER OF RECORD: JACOB H. DUKE


DATE: 01/2023
DATE: 01/2023
DATE: 01/2023



SECTION AT BENT 2

(ANCHOR BOLTS NOT SHOWN FOR CLARITY)
(PROPOSED ANGLES NOT SHOWN FOR CLARITY)


(REMOVE EXISTING DAMAGED ANCHOR BOLTS PRIOR TO ASSEMBLY)



HALF-ELEVATION AT BENT 2

(ANCHOR BOLTS NOT SHOWN FOR CLARITY)





GENERAL BENT 2 PLAN

I-6039 PROJECT NO. NEW HANOVER _ COUNTY

640045 BRIDGE NO._

043777

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION


BEARING REPAIRS

KISINGER CAMPO DOCUMENT NOT CONSIDERED FINAL

301 FAYETTEVILLE ST., SUITE 1500
RALEIGH, NC 27601 (919) 882-7839
NC FIRM LICENSE: C-1506

SUPERSTRUCTURE

SHEET NO REVISIONS S2**-**8 NO. BY: DATE: DATE: BY: TOTAL SHEETS 13



(EBR)

EXPANSION BEARING REPAIRS

(7 ASSEBMLIES REQUIRED - BENT 2)

3½"

5"

(TYP.)

PLAN

4/17/2023 640045_I6039_SMU_BRG01.dgn