## Strain Pole Attachments

## NOTE:

- 1. Strap all signal cables to the side of the pole with  $\sqrt[3]{4}$ " stainless steel straps when the distance between the spanwire attachment clamp and the weatherheads exceeds 3'-0''.
- 2. Provide minimum two spanwire pole clamps per pole.
- 3. It is prohibited to attach two span wires at one pole clamp.
- 4. For general requirements refer to NCDOT Standard Specifications for Roadway and Structures, January 2018.

PROJECT ID. NO. SHEET NO. B-5985A Sig.M6

chme

#4

**\_** 

Strai

ap

- 3-Bolt Clamp with "J" Hook


Pole Band

Messenger Cable

Either 0.05" X 0.30 Aluminum
Ribbon or 0.061" Stainless
Steel Lashing Wire

Interconnect Cable
on Messenger Cable

## Attachment of Cable to Intermediate Metal Pole



## Metal Pole Grounding Detail For Strain Pole and Mast Arm



Typical Fabrication Details For Strain Pole Attachments

Usna Design Section	oci azii i ozo //ccaoniiioneo				
Design Sec	PLAN DATE:	OCTOBER 2017	DESIGNED BY:	C.F.A	NDREWS
eenfleid Pkwy, Garner, NC 27529	PREPARED BY:	N. BITTING	REVIEWED BY:	D.C.	SARKAR
SCALE		REV1S[ONS		INIT.	DATE
O NA					
					<del> </del>
NONE					<del></del>

