

- APPROX. AREA CLASS II

SURFACE PREPARATION

CONCRETE OVERLAY

- SCARIFYING AND SHOTBLASTING

OF BRIDGE DECK FOR POLYMER

- SHOTCRETE REPAIR AREA

BRIDGE NO. 300017 SHEET 1 OF 5 STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SURFACE PREPARATION PLAN OF SPANS

SEAL 054816 William C. Smith

10/24/2023

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

SHEET NO. **REVISIONS** S2-5 NO. BY: DATE: DATE: TOTAL SHEETS

ACTUAL

VOLUME

COUNTY

10/17/2023 R:\Structures\Plans\300017\402_009_B5981_SMU_DSR_A_S2-5_300017.dgn ssandor

ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

NO DECK DEFFICIENCES NOTED DURING FIELD INSPECTION, BECAUSE

THE EXISTING DECK IS COVERED WITH $2\frac{1}{2}$ " ASPHALT WEARING SURFACE. THE CONTRACTOR AND THE ENGINEER SHALL INSPECT THE DECK

_ DATE : 05/2022

DATE : 5/31/23

FOR SECTION A-A AND B-B, SEE "JOINT REPAIR DETAILS" SHEET.

SURFACE AFTER SCARIFICATION.

S. T. SANDOR

W. C. SMITH

DRAWN BY :

CHECKED BY :