





* REMOVE CONCRETE UNTIL SOUND CONCRETE IS FOUND (2"MIN. DEPTH)




SECTION E-E

OVERHANG DETAILS



TYPICAL SECTION



* REMOVE CONCRETE UNTIL SOUND CONCRETE IS FOUND (2"MIN.DEPTH

DAMAGED AREA

NOTE: EXISTING REBAR TO REMAIN IN PLACE. CLEAN, REPAIR AND SPLICE AS NECESSARY.

SECTION F-F

INTERIOR CONCRETE DIAPHRAGM REPAIR DETAILS

NOTES

THE METHOD USED TO DELINEATE THE AREAS OF UNSOUND CONCRETE TO BE REPAIRED SHALL NOT PERMANENTLY MARK THE CONCRETE, LEAVE ANY RESIDUE AFTER REMOVAL OR REQUIRE HARSH CHEMICALS TO REMOVE.

THE CONTRACTOR SHALL REMOVE THE DETERIORATED CONCRETE IN ACCORDANCE WITH THE GUIDELINES SET IN THESE NOTES, IN THE SPECIAL PROVISIONS AND THE STANDARD SPECIFICATIONS.

REMOVE UNSOUND CONCRETE TO THE EXTENT NECESSARY, MINIMUM OF 1"BEHIND REBAR AND MINIMUM OF 2" CLEARANCE TO SAWCUT.

REINFORCING STEEL WHICH IS DETERMINED BY THE ENGINEER TO BE REPLACED, SHALL BE REMOVED TO A POINT WHERE IT IS SOUND. THE PATCH SHALL EXTEND A SUFFICIENT DISTANCE BEYOND THIS POINT TO DEVELOP A SPLICE LENGTH SPECIFIED IN THE TABLE ON THE "DECK REPAIR DETAILS" SHEET.

FOR AREAS TO BE REPAIRED, SEE "DECK UNDERSIDE REPAIR" SHEETS.

THE CONTRACTOR SHALL SUBMIT WORKING DRAWINGS TO THE ENGINEER FOR APPROVAL PRIOR TO STARTING WORK FOR TEMPORARY FORMWORK. FOR SUBMITTALS OF WORKING DRAWINGS, SEE SPECIAL PROVISIONS.

UPON REMOVAL OF TEMPORARY FORMWORK, ALL VOIDS AND HONEYCOMBS ON THE UNDERSIDE OF DECK SURFACE SHALL BE FILLED WITH THE SAME MATERIAL AS USED FOR THE PATCH, AND FINISHED TO CONFORM TO THE SURROUNDING CONCRETE SURFACE.

NO FORMWORK SHALL BE LEFT IN PLACE.

PROJECT NO. B-5981

DUPLIN COUNTY



DEPARTMENT OF TRANSPORTATION
RALEIGH

OVERHANG & DIAPHRAGM REPAIR DETAILS

300017

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED 2 REVISIONS

REVISIONS

REVISIONS

REVISIONS

SHEET NO.

BY:

DATE:

NO. BY:

DATE:

SIGNATURES

SHEET NO.

3

SHEET NO.

4

SHEET NO.

5

SHEET NO.

BRIDGE NO.___

 DRAWN BY:
 S. T. SANDOR
 DATE:
 06/2022

 CHECKED BY:
 W. C. SMITH
 DATE:
 5/31/23

10/17/2023 R:\Structures\Plans\300017\402_049_B5981_SMU_0H&DiaphRepair_S2-25_300017.dgn ssandor