
NC DEPARTMENT OF TRANSPORTATION ATTENTION: BRIDGE CLOSED. SUBMITTED PAR. STRUCTURE DIVISION OF HIGHWAYS STRUCTURE MANAGEMENT UNIT		
Structure Safety Report		
High Water Supplemental		
STRUCTURE NUMBER: 990097 SAP STRUCTURE NO: 1000097 FHWA STRUCTURE NO: 00000001990097		
DIVISION: 13 COUNTY: YANCEY INSPECTION DATE: 10/03/2024 FREQUENCY: None		
FACILITY CARRIED: SR1152 MILE POST:		
LOCATION: .02 MI.S.JCT.SR1201		
EATURE INTERSECTED: SOUTH TOE RIVER		
ATITUDE: <u>35° 52' 16.22"</u> LONGITUDE: <u>82° 11' 48.51"</u>		
SPANS: 3 SPANS. SEE SPAN PROFILE SHEET FOR SPAN DETAILS		
FRACTURE CRITICAL TEMPORARY SHORING SCOUR CRITICAL SCOUR PLAN OF ACTION		
GRADES: (Inspector/NBI Coding) DECK 0/0 SUPERSTRUCTURE 0/0 SUBSTRUCTURE 0/0 CULVERT N/N		
POSTED SV: Not Posted POSTED TTST: Not Posted		

OTHER SIGNS PRESENT:



BRIDGE CLOSED. END BENT 2. COULD NOT ACCESS. (PAR)

INSPECTED BY SIGNATURE Dennis Wilson	ASSISTED BY Josh Ramsey
--------------------------------------	-------------------------



SPAN 1: PRECASTED GIRDER HAS SHIFTED DOWNSTREAM UP TO 2 FEET. (PAR)



SPAN 2 AND SPAN 3 FAILED. SPANS ARE DOWNSTREAM. (PAR)

County: YANCEY

Date: 10/03/2024

Condition Photos



SPAN 2 AND SPAN 3 FAILED. SPANS ARE DOWNSTREAM. (PAR)



SPAN 2 AND SPAN 3 FAILED. SPANS ARE DOWNSTREAM. (PAR)

County: YANCEY

Date: 10/03/2024

Condition Photos



END BENT 1 HAS FAILED. EXPOSED PILES. CAP HAS WIDE CRACKS AND SPALLED AREAS. (PAR)



END BENT 1 HAS FAILED. EXPOSED PILES. CAP HAS WIDE CRACKS AND SPALLED AREAS. (PAR)

County: YANCEY

Date: 10/03/2024

Condition Photos



END BENT 1 HAS FAILED. EXPOSED PILES. CAP HAS WIDE CRACKS AND SPALLED AREAS. (PAR)



BRIDGE CLOSED. END BENT 2. COULD NOT ACCESS. (PAR)

County: YANCEY

Date: 10/03/2024

Condition Photos



INTERIOR BENT 2 FAILED. (PAR)



INTERIOR BENT 2 FAILED. (PAR)

County: YANCEY

Date: 10/03/2024

Condition Photos



SPAN 1 DRIFT. (PAR)



SPAN 1 DRIFT. (PAR)