



332A CABINET  
LEFT SIDE

332A CABINET

332A CABINET  
RIGHT SIDE

**REAR VIEW**

**NOTE**

-PROVIDE A 2 " SPACE BETWEEN THE CONTROLLER AND THE ROLL OUT DRAWER TO ACCOMMODATE A FIBER INTERCONNECT CENTER.

Typical Drawing

	<p><b>Cabinet Component Layout</b> 170 Cabinet Model 332A with 2070L Controller</p>	<p>SEAL 16286</p>								
	<p>Division 8      Lee County      Sanford</p>									
	<p>PLAN DATE: <b>October 2002</b>      REVIEWED BY:</p>									
	<p>PREPARED BY: <b>P L Alexander</b>      REVIEWED BY:</p>									
<p>REVISIONS</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>NO.</th> <th>DESCRIPTION</th> <th>INIT.</th> <th>DATE</th> </tr> </thead> <tbody> <tr> <td> </td> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table>	NO.	DESCRIPTION	INIT.	DATE						
NO.	DESCRIPTION	INIT.	DATE							
<p>222 N. McDowell St., Raleigh, NC 27603</p>	<p><i>Milton I. Dean</i> 11/13/02 SIGNATURE      DATE</p>	<p>SIG. INVENTORY NO.      NA</p>								

13-M01-2002 10:48  
U:\p00d\170 cab\rear.dgn  
plalexander