



DITCH CLEAN OUT: -L- STA. 20+80 LT.  
 2' BASE DITCH CLEANOUT: L=18', s=0.3%, DDE=19 CY

MATCHLINE -L- STA.20+50 SEE SHEET 5

MATCHLINE -L- STA.26+00 SEE SHEET 7

REMOVE ALL CONSTRUCTION DEBRIS AND BACKFILL MEDIAN WITH TOPSOIL

FOR -L- PROFILE SEE SHEET 43

NOTE: SEE MB 35 PG 321 FOR TIES, BEARINGS AND DISTANCES.  
 NOTE: CB #0504 LOCATED 3.8 FT NORTH OF SAG ON -L-

NOTE: SEE MB 35 PG 321 FOR TIES, BEARINGS AND DISTANCES.  
 NOTE: SEE MB 35 PG 321 FOR TIES, BEARINGS AND DISTANCES.

TEMPORARY GUARDRAIL WILL BE INSTALLED IMMEDIATELY UPON REMOVAL OF CONCRETE WALL

RPP HOLDINGS, LLC  
 DB 5751 PG 91  
 DB 1282 PG 1856  
 DB 1460 PG 843  
 MB 13 PG 33  
 DB 5644 PG 2770  
 DB 5684 PG 787  
 DB 5645 PG 2278

RPP HOLDINGS, LLC  
 DB 5751 PG 91  
 DB 1088 PG 854  
 DB 5644 PG 2770  
 DB 5684 PG 787  
 DB 5645 PG 2278

RPP HOLDINGS, LLC  
 DB 5751 PG 91  
 DB 1088 PG 854  
 DB 5644 PG 2770  
 DB 5684 PG 787  
 DB 5645 PG 2278

RPP HOLDINGS, LLC  
 DB 5751 PG 91  
 DB 1088 PG 854  
 DB 5644 PG 2770  
 DB 5684 PG 787  
 DB 5645 PG 2278

RPP HOLDINGS, LLC  
 DB 5751 PG 91  
 DB 1282 PG 1856  
 DB 1460 PG 843  
 MB 13 PG 33  
 DB 5644 PG 2770  
 DB 5684 PG 787  
 DB 5645 PG 2278

S & D FOSTER FAMILY, LLC.  
 DB 2399 PG 756  
 MB 35 PG 321

WILLIAM R. JONES, ET UX  
 DB 3031 PG 665  
 MB 35 PG 321

WILLIAM M. STOCKS, ET UX  
 DB 3080 PG 031  
 MB 35 PG 321

PATRICIA C. WILLIAMS  
 DB 2113 PG 404  
 MB 35 PG 321

THOMAS P. WHITE  
 DB 4836 PG 301  
 MB 35 PG 321

CHARLES WHITE, ET UX  
 DB 504 PG 1694  
 MB 35 PG 321

GREENWAY VILLAGE HOMEOWNERS ASSOC. INC.  
 DB 2621 PG 553  
 DB 2378 PG 054  
 MB 25 PG 56  
 MB 671 PG 597 1/2  
 MB 35 PG 320  
 MB 35 PG 321  
 MB 35 PG 369  
 MB 36 PG 189  
 MB 36 PG 91  
 MB 36 PG 283

LINDA P. ALSTON, ET VIR  
 DB 1236 PG 1881  
 MB 671 PG 597 1/2

LETHIA S. HANKINS  
 DB 1282 PG 1807  
 MB 671 PG 597 1/2

CARL O. SANDERS, ET UX  
 DB 713 PG 267  
 MB 671 PG 597 1/2  
 MB 35 PG 320

03-FEB-2015 10:10 \\N:\3338B\_rdl.psh.s06.dgn

REVISIONS

8/17/99