





110

"Stretch" Operation











Volume Density Operation



Presence Loop Placement at Stop Lines



Quadrupole loops: Use 2-4-2 turns Single 6' X 6' loop 6' X 15' Loops: Lead-in < 150', use 2 turns Lead-in > 150', use 3 turns

Recommended Number of Turns

