

DocuSign Envelope ID: 34E2C66B-7797-4AB6-9BD3-31F0D6E698EB

+

NOTES:

FOR DETAILS AND NOTES, SEE "HANDRAIL DETAILS" SHEET 2 OF 2. FOR "SECTION A-A", SEE "HANDRAIL DETAILS" SHEET 2 OF 2.

- INDICATES END POST REQUIRED AT THIS LOCATION. SEE "END POST DETAIL" ON SHEET 2 OF 2.
- ▼ INDICATES RAIL EXPANSION JOINT (SPLICE GAP). SEE ``RAIL EXPANSION JOINT DETAIL" ON SHEET 2 OF 2.

SEE "HANDRAIL POST-SPACING - WINGWALLS" DETAIL ON SHEET 2 OF 2

| | PROJECT NO. <u>U-3308</u> <u>DURHAM</u> COUNTY STATION: <u>24+55.20</u> -LALT- I3+22.18 -CSXN- SHEET 1 OF 2 |
|---|---|
| S E AL 25911 WGINEER MGINEER | STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH |
| Docusigned by: Dwain Hathaway 283786071DA0460 5/3/2016 | HANDRAIL AND POST SPACING |
| Michael Boker Engineering | REVISIONS SHEET NO. |
| Michael Baker Engineering 8000 Regency Parkway, Suite 600 | NO. BY: DATE: NO. BY: DATE: S4-25 |
| Cary, North Carolina 276518 NC License No. : F-1084 | 1 3 TOTAL SHEETS 2 4 68 |