

31-MAR-2016 06:25 R:\Structures\DGN\402\_025\_I5789\_SMU\_S11\_SP.DGN ssandor

+

+

SUMMARY OF	QUANTIT	IES
	ESTIMATE	ACTUAL
CONCRETE DECK REPAIR FOR EPOXY OVERLAY	10 SQ.FT.	
BRIDGE JOINT DEMOLITION	115 SQ.FT.	
EPOXY OVERLAY SYSTEM	9600 SQ.FT.	

FOR BRIDGE JOINT DEMOLITION, SEE "JOINT DETAILS" SHEET. FOR SECTIONS A-A AND B-B, SEE "JOINT DETAILS" SHEET.

CONCRETE DECK REPAIR EPOXY OVERLAY IS NOT ANTICIPATED.TOKEN PAY ITEM IS INDICATED FOR PRICING PURPOSES.IN CASE UNANTICIPATED REPAIR AREAS ARE ENCOUNTERED.



EPOXY OVERLAY

BRIDGE JOINT DEMOLITION

		UILF	0	RD	<u>-5789</u> co .11	) UNTY
Unit CARO SESSOLA MUNICISEAL MONES MONES MONES MONES	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH SURFACE PREPARATION AND EPOXY OVERLAY					
	REVISIONS SHEET NO.				SHEET NO.	
MENT NOT CONSIDERED	NO. BY:	DATE:	NO.	BY:	DATE:	S-11
FINAL UNLESS ALL	1		3			SHEETS
GNATURES COMPLETED	2		4			37