




DETAILS OF REPAIRING EXISTING PAVEMENT PRIOR TO RESURFACING FOR FULL DEPTH AND MILLING




DETAIL NO. 1




DETAIL NO. 2




DETAIL NO. 3



DETAIL NO. 4



DETAIL NO. 5



DETAIL FOR INCIDENTAL MILLING:  
BEGINNING AND/OR END OF MAP & BRIDGES

REVISIONS

8/17/99  
 06 JUL -2016 11:41  
 Resurfacing\Sampson Co\2017CPT.03.02.10821.NC.242 & NC.411\2017CPT.03.02.20821.Etc.Rdy\_TYP.dgn