

27-SEP-2016 14:36 R:\Structures\FinalDrawings\McDowell152\I-5809_SD-GD*152.dgn

+

+

NOTES

PROFILE INFORMATION IS TAKEN FROM THE ORIGINAL PLANS AND THE ROUTINE INSPECTION REPORT DATED 04/15/2014. BRIDGE ORIENTATION CONFORMS TO EXISTING BRIDGE PLANS.

SCOPE OF WORK

CLEAN AND PAINT STEEL I-BEAMS AND BEARINGS.
EPOXY INJECTION OF CONCRETE CRACKS.
CLEAN AND REPAIR REBAR IN CONCRETE REPAIR AREAS.
PERFORM CONCRETE REPAIRS IN PREPARED AREAS.
REMOVE DEBRIS FROM TOP OF BENT CAPS AND APPLY EPOXY COATING.
PARTIALLY REMOVE BRIDGE DECK CONCRETE USING SHOTBLASTING METHODS.
OVERLAY PREPARED BRIDGE DECK WITH EPOXY OVERLAY SYSTEM.
RECONSTRUCT BRIDGE JOINTS AND INSTALL JOINT SEALS.

APPROACH SLAB

	PROJECT NO. <u>I-5809</u> <u>McDOWELL</u> COUNTY BRIDGE NO. <u>152</u> SHEET 1 OF 2					
SEAL 32492 MINER YANNA 16	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH GENERAL DRAWING FOR BRIDGE ON I-40 WBL OVER SR 1760 (HARMONY GROVE ROAD)					
	REVISIONS					SHEET NO.
ENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY	•	DATE:	S-48
NAL UNLESS ALL ATURES COMPLETED	1		3 A			TOTAL SHEETS 68