
U-4715B ITS-5.03

POLE-MOUNTED SIGNAL CABINET DETAIL

METAL POLE

WOOD POLE



PREPARED BY: A M Quigley

REVISIONS

0 Greenfield Parkway, Garner, NC 2752

N.T.S.

REVIEWED BY: JT Brooks

INIT. DATE