

AS-BUILT REPAIR QUANTITY TABLE TOP OF DECK REPAIRS ESTIMATE ACTUAL SCARIFYING BRIDGE DECK 588 SQ. YDS. CLASS II SURFACE PREPARATION 14.0 SQ. YDS. 14.0 SQ. YDS. CONCRETE DECK REPAIR FOR PPC OVERLAY 588 SQ. YDS. SHOTBLASTING BRIDGE DECK PPC MATERIALS 20.4 CU. YDS. PLACING AND FINISHING PPC OVERLAY 588 SQ. YDS. GROOVING BRIDGE FLOORS 5014 SQ.FT.


TOP OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF CLASS II SURFACE PREPARATION AND CONCRETE DECK REPAIR FOR PPC OVERLAY AFTER REMOVAL OF UNSOUND CONCRETE (MIN. 2"CLEAR TO SAWCUT). SEE OVERLAY SURFACE PREPARATION FOR POLYESTER POLYMER CONCRETE SPECIAL PROVISION.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR SECTION A-A, SEE "JOINT DETAILS" SHEETS.

Nicholas Pierce



CLASS II SURFACE PREPARATION

PROJECT NO. I-5825

MECKLENBURG COUNTY

BRIDGE NO. 213

SHEET 2 OF 3

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION

RALEIGH

PLAN OF SPAN

SPAN B

REVISIONS

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

REVISIONS

NO. BY: DATE: NO. BY: DATE: S-14

TOTAL SHEETS

31

02-MAR-2018 13:35 B:\TIPProjects-I\I5825\Structures\FinalPlans\402_003_I5825_SMU_ S2_014_590213.dgn napierce

__ DATE : <u>12/17</u> __ DATE : <u>1/18</u>

E.K.POPE

A. SORSENGINH

DRAWN BY : .

CHECKED BY :