

PLAN

AS-BUILT REPAIR Q	YTITMAL	TABLE	
TOP OF DECK REPAIRS			
	ESTIMATE	ACTUAL	
SCARIFYING BRIDGE DECK	295 SQ. YDS.		
CLASS II SURFACE PREPARATION	* 0.5 SQ. YDS.		
CONCRETE DECK REPAIR FOR PPC OVERLAY	* 0.5 SQ. YDS.		
SHOTBLASTING BRIDGE DECK	295 SQ. YDS.		
PPC MATERIALS	10.3 CU. YDS.		
PLACING AND FINISHING PPC OVERLAY	295 SQ. YDS.		
GROOVING BRIDGE FLOORS	2283 SQ.FT.		

TOP OF DECK REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF CLASS II SURFACE PREPARATION AND CONCRETE DECK REPAIR FOR PPC OVERLAY AFTER REMOVAL OF UNSOUND CONCRETE (MIN. 2"CLEAR TO SAWCUT). SEE OVERLAY SURFACE PREPARATION FOR POLYESTER POLYMER CONCRETE SPECIAL PROVISION.

NOTES:

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE AS-BUILT REPAIR QUANTITY TABLE.

FOR SECTIONS A-A AND B-B, SEE "JOINT DETAILS" SHEET.

*CLASS II SURFACE PREPARATION AND CONCRETE REPAIR FOR PPC OVERLAY ARE NOT ANTICIPATED. A TOKEN PAY ITEM IS INDICATED FOR PRICING PURPOSES IN THE EVENT UNANTICIPATED CLASS II AREAS ARE ENCOUNTERED.

PROJECT NO. I-5825

MECKLENBURG COUNTY

BRIDGE NO. 215

SHEET 4 OF 4

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION
RALEIGH

PLAN OF SPAN

SPAN D AND
APPROACH ROADWAY 2

DocuSigned by:

Nicholas Pierce

15110B434D0B485...

SEAL 037479

15110B43	4D0B485	
		CONSIDERED
		ESS ALL
STGNAID	KF2	COMPLETED

APPROACH ROADWAY 2

REVISIONS SHEET NO.
BY: DATE: NO. BY: DATE: S-22

TOTAL SHEETS

DRAWN BY: E.K.POPE DATE: 1/18
CHECKED BY: N.A.PIERCE DATE: 1/18