

AS-BUILT REPAIR QUANTITIES TABLE																	
BRIDGE No. 590227		#57 STONE		CHAIN LINK FENCE, 72"FABRIC		METAL LINE POSTS FOR 72"CHAIN LINK FENCE		METAL TERMINAL POSTS FOR 72" CHAIN LINK FENCE		RIP RAP CLASS B (1'-0" THICK)		GEOTEXTILE FOR DRAINAGE		GABION MATTRESSES (1'-0" THICK)		CLASS A CONCRETE	
	ESTIMATED	ACTUAL	ESTIMATED	ACTUAL	ESTIMATED	ACTUAL	ESTIMATED	ACTUAL	ESTIMATED	ACTUAL	ESTIMATED	ACTUAL	ESTIMATED	ACTUAL	ESTIMATED	ACTUAL	
	TON	TON	LIN.FT.	LIN.FT.	EACH	EACH	EACH	EACH	TON	TON	SQUARE YARDS	SQUARE YARDS	SQ.YDS.	SQ.YDS.	CU.FT.	CU.FT.	
END BENT 1	38		155		14		12		848		1,766		1,766			6.8	
END BENT 2	34		155		14		12		795		1,885		1,885			54.0	
TOTAL	72		310		28		24		1,643		3,651		3,651			60.8	

_ DATE : 08/2018 _ DATE : 12/2018 N.A. PIERCE DRAWN BY : . D.A. CANTRELL CHECKED BY :

		REVISIONS								
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:				
FINAL UNLESS ALL	1			8						
SIGNATURES COMPLETED	2			4						

BRIDGE NO.___

SEAL 35647 ANGINEER A. 12/6/2019

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

590227

SHEET NO S3-13

TOTAL SHEETS

SLOPE PROTECTION REPAIR DETAILS