



Map 2 SR 2135 S Jim Minor Rd
 Incidental Mill to Tie into NC 119
 DO NOT PAVETHROUGH NC 119
 Incidental Mill at Bridge #82 Bridge Approaches
 Mill and Fill 1-1/2" on Bridge #82
 Resurface Bridge #83