



Map 5 SR 2327 Bass Mountain Rd
 Incidental Mill at Bridge #125 Bridge Approaches
 Mill and Fill 1-1/2" on Bridge #125