




JOINT INSTALLATION SEQUENCE AT BENTS (SECTION B-B)



PLAN





5430 Wade Park BLVD, Suite 410

Tel. 919-854-0344 Fax. 919-854-0355

Raleigh, NC 27607

NC License No. F-0765

FOAM JOINT SEAL TO BE CUT, HEAT WELDED AND TURNED UP PARALLEL TO SLOPED FACE OF THE SIDEWALK.

JOINT SEAL DETAILS @ BENT

* FOAM JOINT SEALS FOR PRESERVATION SHALL BE RECESSED AS PER MANUFACTURER'S RECOMMENDATIONS.

DETAIL B

JOINT REPAIR QUANTITY					
	ESTIMATED (LIN.FT.)	ACTUAL (LIN. FT.)			
FOAM JOINT SEALS FOR PRESERVATION	393.8				

SAWED JOINT OPENING TABLE					
LOCATION	SKEW ANGLE	PERPENDICULAR JOINT OPENING AT 45°	PERPENDICULAR JOINT OPENING AT 60°	PERPENDICULAR JOINT OPENING AT 90°	
* END BENT 1	129°28′04 . 3″	2 11/16"	2 11/16"	2 11/16"	
BENT 1	131°07′58″	1 5/8"	1 ⁹ / ₁₆ "	1 7/16"	
BENT 2	132°04′57″	1 5/8"	1 %i6"	1 1/2"	
BENT 3	133°02′17″	1 5/8"	1 %i6"	1 1/2"	
BENT 4	133°59′50″	1 5/8"	1 % "	1 1/2"	
BENT 5	135°22′29″	1 5/8"	1 ⁹ / ₁₆ "	1 3/8"	
*END BENT 2	136°11′22.9″	2 "/16"	2 11/16"	2 11/16"	

SEAL 025516 CHONEER 1/11/2023

SIGNATURES COMPLETED

I-5927 PROJECT NO._ POLK COUNTY BRIDGE NO: ___740048

> STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

> > RALEIGH

DETAILS

79

JOINT REPAIR

SHEET NO. REVISIONS S-39 DATE: DATE: NO. BY: BY: DOCUMENT NOT CONSIDERED FINAL UNLESS ALL TOTAL SHEETS

SHEET 2 OF 2

_ DATE : 7/21 D. A. GLADDEN DRAWN BY : __ DATE : 12/22 E. MURRAY CHECKED BY : .

** EXISTING FORMED JOINTS AT END BENTS ARE ANTICIPATED TO BE 1 3/4 AT 60 DEGREES.FIELD VERIFY AND PROVIDE NOMINAL UNCOMPRESSED SEAL WIDTH BASED ON JOINT OPENINGS.