




## JOINT INSTALLATION SEQUENCE AT BENTS (SECTION B-B)







## JOINT REPAIR QUANTITY ESTIMATED ACTUAL (LIN.FT.) (LIN.FT.) FOAM JOINT SEALS FOR PRESERVATION 393.8

## JOINT SEAL DETAILS @ BENT

FOAM JOINT SEAL TO BE CUT, HEAT WELDED AND TURNED UP PARALLEL TO SLOPED FACE OF THE SIDEWALK.

\* FOAM JOINT SEALS FOR PRESERVATION SHALL BE RECESSED AS PER MANUFACTURER'S RECOMMENDATIONS.

DETAIL B

SAWED JOINT OPENING TABLE					
LOCATION	SKEW ANGLE	PERPENDICULAR JOINT OPENING AT 45°	PERPENDICULAR JOINT OPENING AT 60°	PERPENDICULAR JOINT OPENING AT 90°	
* END BENT 1	129°43′58.3″	2 11/16"	2 11/16"	2 11/16"	
BENT 1	131°06′24″	1 5/8"	1 <sup>9</sup> / <sub>16</sub> "	1 7/16"	
BENT 2	132°04′07″	1	1 % <sub>6</sub> "	1 1/2"	
BENT 3	133°56′56″	1 5/8"	1 % <sub>6</sub> "	1 1/2"	
BENT 4	133°53′47″	1	1 %i6"	1 1/2"	
BENT 5	135°24′02″	1 5/8"	1 %i6"	1 <sup>3</sup> ⁄8″	
* END BENT 2	136°17′40 <b>.</b> 5″	2 11/16"	2 11/16"	2 11/16"	

PROJECT NO. I-5927 POLK COUNTY 740050 BRIDGE NO: \_

SHEET 2 OF 2

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH

> JOINT REPAIR DETAILS

Tel. 919-854-0344 Fax. 919-854-0355

NC License No. F-0765

VOLKERT	
5430 Wade Park BLVD, Suite 410 Raleigh, NC 27607	DO

	REVISIONS			SHEET NO.			
CUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-63
FINAL UNLESS ALL	1			3			TOTAL SHEETS
IGNATURES COMPLETED	2			4			79

DRAWN BY : _	D. A. GLADDEN	DATE :	7/21
CHECKED BY :	E. MURRAY	DATE :	12/22

\*\* EXISTING FORMED JOINTS AT END BENTS ARE ANTICIPATED TO BE 1 ¾ AT 60 DEGREES.FIELD VERIFY AND PROVIDE NOMINAL UNCOMPRESSED SEAL WIDTH BASED ON JOINT OPENINGS.