

6/22/2023 R:\Structures\Plans\15BPR124\404\_011\_15BPR124\_SMU\_DSR04\_S4-06\_911084.dgn aygodfrey

+

+

## DECK SURFACE REPAIR QUANTITY TABLE

SPAN D

	ESTIMATE	ACTUAL
CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT	0.0 CU. FT	
CONCRETE REPAIR	2.5 CU.FT.	
SHOTBLASTING BRIDGE DECK	1154.4 SQ. YDS.	
SILANE DECK TREATMENT	1154.4 SQ. YDS.	
BRIDGE JOINT DEMOLITION	69.0 SQ.FT.	
SURFACE PREPARTAION FOR CONCRETE BARRIER RAIL	797.0 SQ.FT.	
SILANE BARRIER RAIL TREATMENT	797.0 SQ.FT.	

## APPROACH SLAB


	ESTIMATE	ACTUAL
CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT	0.0 CU. FT	
CONCRETE REPAIR	0.0 CU.FT.	
SHOTBLASTING BRIDGE DECK	29.4 SQ. YDS.	
SILANE DECK TREATMENT	29.4 SQ. YDS.	
BRIDGE JOINT DEMOLITION	69.0 SQ. FT.	
SURFACE PREPARTAION FOR CONCRETE BARRIER RAIL	136.0 SQ.FT.	
SILANE BARRIER RAIL TREATMENT	136.0 SQ.FT.	

## NOTES

DECK SURFACE REPAIR QUANTITIES REPRESENT ESTIMATED VALUES OF CLASS II SURFACE PREPARATION AND CONCRETE DECK REPAIR AFTER REMOVAL OF UNSOUND CONCRETE. (MIN. 2" CLEAR TO SAWCUT). SEE CONCRETE FOR DECK REPAIR SPECIAL PROVISION.

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE REPAIR QUANTITY TABLE.

FOR SECTION A-A, SEE "FOAM JOINT SEALS FOR PRESERVATION DETAILS" SHEET.



CONCRETE REPAIR AREA

BRIDGE JOINT DEMO

	PROJEC	WAK	E	PR.12 CO 11084	<b>4.3</b> UNTY	
SEAL of ESSION AND SEAL OF ESSION AND SEAL OF ESSION AND SEAL OF ESSION AND SEAL OF THE ADDRESS	STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH DECK SURFACE REPAIR SPAN D AND APPROACH SLAB					
	REVISIONS SHEET NO.					
DOCUMENT NOT CONSIDERED	NO. BY:	DATE:	NO. BY:	DATE:	S4-06	
FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		<u> ৩</u> ব্র		TOTAL SHEETS 21	