


DESIGN ENGINEER OF RECORD: DATE :	CHECKED BY :	A. SORSENGINH	DATE : (
	DESIGN ENGINEER	OF RECORD:	DATE :_

+

+

9/15/2023 S:\DPG3\15BPR.125.3\Final Plans\402_031_15BPR125_3_SMU_DUR_S16_190010.dgn ksedai



SPAN D

AS-BUILT REPAIR QUANTITY TABLE							
DECK UNDERSIDE REPAIRS	QUANTITIES						
SPAN D	ESTIMATE		ACTUAL				
SHOTCRETE REPAIRS	AREA VOLUME SF CF		AREA SF	VOLUME CF			
UNDERSIDE OF DECK	0	0					
CONCRETE DIAPHRAGM	0.5	0.3					
OVERHANG	0	0					
CONCRETE GIRDER	0	0					
CONCRETE REPAIRS	AREA VOLUME SF CF		AREA SF	VOLUME CF			
UNDERSIDE OF DECK	0	0					
CONCRETE DIAPHRAGM	0 0						
OVERHANG	0	0					
CONCRETE GIRDER	0	0					
EPOXY RESIN INJECTION	LINEAR FT		LINEAR FT				
UNDERSIDE OF DECK	1.3						

VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN. 2" CLEAR TO SAWCUT. SEE REPAIR DETAILS.

NOTES

REPAIR LOCATIONS AND ESTIMATE OF QUANTITIES ARE GIVEN BASED ON THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER SHALL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATION AND DESCRIPTION OF THE REPAIRS AND ENTER THE ACTUAL QUANTITIES INTO THE REPAIR QUANTITY TABLE.

SHOTCRETE REPAIRS MAY BE REPLACED WITH CONCRETE REPAIRS WITH THE APPROVAL OF THE ENGINEER.

FOR SHOTCRETE REPAIRS, SEE SPECIAL PROVISIONS.

CONTRACTOR SHALL SAWCUT TO A NOMINAL DEPTH OF 1/2" BUT REINFORCING STEEL SHALL NOT BE DAMAGED.

CONTRACTOR SHALL REMOVE SURFACE CONCRETE TO VERIFY THAT SAWCUT DEPTH WILL NOT DAMAGE EXISTING REINFORCING STEEL.

FOR UNDERSIDE OF DECK AND OVERHANG REPAIRS, SEE "OVERHANG, DIAPHRAGM AND BRIDGE RAIL REPAIR DETAILS" SHEET.

PRIOR TO CLEANING AND PAINTING, REPLACE AND/ OR TIGHTEN MISSING NUTS AND WASHER.

PAYMENT FOR REPLACING AND/OR TIGHTENING WASHERS AND NUTS SHALL BE CONSIDERED INCIDENTAL TO VARIOUS PAY ITEMS.

	SHOTCRETE REPAIR ARE	4				
\frown	EPOXY RESIN INJECTION	PROJEC	T NO	15BF	PR.125	5.3
TN	TIGHTEN NUT			OKEE	CO	UNTY
RW	REPLACE WASHER	BRIDGE SHEET 4 OI		19	0010	
	SE AL O31583 Docusigned Han Krishna P. Sedai EA6F794150BF487. 09/15/2023		RTMENT	RALEIGH	NSPORTA	TION
		NO. BY:	REVISI		DATE:	SHEET NO. S2-16
	DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED	1 2		NO. BY: 3 4		TOTAL SHEETS 28