Sig. 11.6

PHASING DIAGRAM OASTS 2070 LOOP & DETECTOR INSTALLATION CHART TABLE OF OBERATION

Ø2+6 Ø4	
Ø2+5	

PHASING DIAGRAM DETECTION LEGEND

DETECTED MOVEMENT

UNSIGNALIZED MOVEMENT

UNDETECTED MOVEMENT (OVERLAP)

TABLE OF OPERATION						
	PHASE					
SIGNAL FACE	Ø2+5	Ø2+6	Ø 4	FLAST		
21, 22	G	G	R	Υ		
41,42,43	R	R	G	R		
51, 52	-	+	+	*		
61, 62	R	\uparrow	R	Y		

OASIS 2070 LOOP & DETECTOR INSTALLATION CHA							AR	T				
INDUCTIVE LOOPS				DETECTOR PROGRAMMING								
LOOP	SIZE (FT)	DISTANCE FROM STOPBAR (FT)	TURNS	NEW LOOP	PHASE	CALLING	EXTENSION	FULL TIME DELAY	STRETCH TIME	DELAY TIME	SYSTEM LOOP	NEW CARD
2A,2B	*	300	*	*	2	Υ	Υ	-	1.6	_	-	*
2C,2D	*	90	*	*	2	Υ	Υ	_	-	_	-	*
4 A	*	0	*	*	4	Υ	Υ	_	-	_	-	*
4B	*	0	*	*	4	Υ	Υ	-	1	_	-	*
5A	*	0	*	*	5	Υ	Υ	_	1	_	-	*
5B	*	0	*	*	5	Υ	Υ	_	_	_	-	*
6A,6B	*	300	*	*	6	Υ	Υ	_	1.6	_	-	*
6C,6D	*	90	*	*	6	Υ	Y	_	-	_	-	*

st Video Detection Zone

Fully Actuated (Isolated)


3 Phase


NOTES


- 1. Refer to "Roadway Standard Drawings NCDOT" dated January 2018 and "Standard Specifications for Roads and Structures" dated January 2018.
- Do not program signal for late night operation unless otherwise directed by the Engineer.
- 3. Phase 5 may be lagged.
- 4. Set all detector units to presence mode.
- This intersection uses video detection. Install detectors according to the manufacturer's instructions to schieve the desitred detection.
- Refer to Pavement Marking Plans for proposed stop bar locations
- 7. Reposition existing signal heads as shown on the plans.

SIGNAL FACE I.D. All Heads L.E.D.

 $<\!\!--\!\!>$ PEDESTRIAN MOVEMENT







* These values may be field adjusted. Do not adjust Min Green and Extension times for phases 2 and 6 lower than what is shown. Min Green for all other phases should not be lower than 4 seconds.


-


ON

17/20|| 9:38:53 AM \Traffic\Signals

Dual Entry

Simultaneous Gap







US 421 US 421 Business

	Divsion 11	Wilkes Co	unty	Wilkesbo				
	PLAN DATE:	May 2023	REVIEWED BY:	M.L. Stygles				
9	PREPARED BY:	S.R. Chiluka	REVIEWED BY:	J. Ma				
		REVISIONS		INIT.	DATE			

750 N.Greenfield Pkwy, Garner, NC 27529 1"=40'

SEAL 047250

DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED

SIG. INVENTORY NO. |--||4674