+

+

	TOTAL BILL OF MATERIAL																			
BRIDGE NO.	GROOVING BRIDGE FLOORS	CLEANING & PAINTING OF EXISTING WEATHERING STEEL BRIDGE No	PAINTING CONTAINMENT FOR BRIDGE No	POLLUTION CONTROL	CLASS II SURFACE PREPARATION	POLYESTER POLYMER CONCRETE MATERIALS	EPOXY POLYMER CONCRETE MATERIALS (ALTERNATE)	PLACING & FINISHING POLYMER CONCRETE OVERLAY	CONCRETE REPAIRS	SHOTCRETE REPAIRS	EPOXY RESIN INJECTION	FOAM JOINT SEALS FOR PRESERVATION	POURABLE SILICONE JOINT SEALANT	BRIDGE JOINT DEMOLITION	EPOXY COATING	CONCRETE DECK REPAIR FOR POLYMER CONCRETE OVERLAY	BEAM REPAIR - PLATING	SURFACE PREPARATION FOR CONCRETE BARRIER	SILANE BARRIER RAIL TREATMENT	SILANE DECK TREATMENT
	SQ.FT.	LUMP SUM	LUMP SUM	LUMP SUM	SQ. YDS.	CU. YDS.	CU.YDS.	SQ.YDS.	CU.FT.	CU.FT.	LN.FT.	LN.FT,	LN.FT.	SQ.FT.	SQ.FT.	SQ. YDS.	LBS.	SQ.FT.	SQ.FT.	SQ.YD.
310108	17,992	LUMP SUM	LUMP SUM	LUMP SUM	26.0	103	103	2,105	-	98.1	254.5	175	-	-	731	26.0	-	1,764	1,764	-
310112	15,956	LUMP SUM	LUMP SUM	LUMP SUM	24.0	91	91	1,879	12.0	257.0	363	156	-	-	668	24.0	-	1,797	1,797	-
310135	-	LUMP SUM	LUMP SUM	LUMP SUM	-	-	-	-	4.0	133.0	123	73 <del>*</del>	-	95 <del>*</del>	1,234	-	-	5,046	5,046	3,985
310355	10,716	LUMP SUM	LUMP SUM	LUMP SUM	22.0	63.5	63.5	1,304	0.3	115.0	347	150	169	-	830	22.0	306	1,776	1,776	-
310429	27,461	LUMP SUM	LUMP SUM	LUMP SUM	56.0	165	165	3,383	1.3	658.8	552.5	386	200	-	2,434	56.0	-	4,980	4,980	-
TOTAL	72,125	LUMP SUM	LUMP SUM	LUMP SUM	128.0	422.5	422.5	8,671	17.6	1,261.9	1,640	940	369	95	5,897	128.0	306	15,363	15,363	3,985

\* FOR END BENT 2 JOINT ONLY

TOTAL BILL OF MATERIAL									
BRIDGE NO.	FLOWABLE FILL	SCARIFYING BRIDGE DECK	SHOTBLASTING BRIDGE DECK	ELASTOMERIC CONCRETE FOR PRESERVATION					
	CU.YD.	SQ. YDS.	SQ.YDS.	CU.FT.					
310108	-	2,105	2,105	-					
310112	-	1,879	1,879	-					
310135	1.4	_	3,985	32.0					
310355	-	1,304	1,304	-					
310429	_	3,383	3,383	-					
TOTAL	1.4	8,668	12,653	32.0					

DRAWN BY :	M. HOGAN	DATE : <u>3/2023</u>
CHECKED BY :	JIA XU	DATE : <u>7/2023</u>
DESIGN ENGINEER	OF RECORD: F.ASEFNIA	DATE : <u>11/2023</u>

## NOTE:

AT THE TIME OF PREPARATION OF THESE PLANS,IT WAS NOT ANTICIPATED THAT ITEM(S)LISTED BELOW WOULD BE REQUIRED.HOWEVER,IT MAY BE DETERMINED IN THE FIELD THAT THE FOLLOWING ITEM(S)LISTED, OR OTHER WORK WILL BE NECESSARY TO PROPERLY COMPLETE THE INTENDED BRIDGE PRESERVATION/REHABILITATION WORK. THE CONTRACTOR SHALL BE PREPARED TO PERFORM SUCH WORK IN A TIMELY MANNER, AS DETERMINED IN THE FIELD. SUCH WORK SHALL BE CONSIDERED EXTRA WORK AND SHALL BE ADDRESSED AS PER ARTICLE 104-7 OF THE STANDARD SPECIFICATIONS.PROJECT SPECIAL PROVISIONS THAT OUTLINE REQUIREMENTS FOR THESE POTENTIAL ADDITIONAL WORK ITEMS HAVE BEEN PROVIDED IN THE PROJECT DOCUMENTS, BUT NO QUANTITIES HAVE BEEN LISTED. ACTUAL PAY ITEMS, QUANTITIES, AND COSTS WILL BE ESTABLISHED, AS REQUIRED, IF EXTRA WORK IS ENCOUNTERED. UNANTICIPATED ITEMS: CLASS III SURFACE PREPARATION

CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT CONCRETE FOR DECK REPAIR VOLUMETRIC MIXER

	PROJECT NO. <u>I</u> DURHAM BRIDGE NO. 310108, 310135, 3103 SHEET 1 OF 1	<u> </u>			
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED DocuSigned by: HAV JIV ASERIA 19141A6AF2E702 TH CAROL SE AL 20103 SE AL 20103	STATE OF NORTH CAROL DEPARTMENT OF TRAN RALEIGH TOTAL B OF MATEF	SPORTATION			
	REVISIONS SHEET NO.				
E.L. ROBINSON E N G I N E E R I N G LE N G I N E E R I N G Li 984.960.2810 elrobinsonengineering.com License: C-22 9	NO. BY: DATE: NO. BY:   1 3   2 4	DATE: S-1 TOTAL SHEETS 74			