
REPAIR KEY




- SHOTBLASTING AND SILANE DECK TREATMENT



CONCRETE DECK REPAIR FOR SILANE DECK TREATMENT



- BRIDGE JOINT DEMOLITION



DRAWN BY :	G. AYES	DATE : 11/2022
CHECKED BY :	A. G. ABRAHA	DATE: 11/2022
DESIGN ENGINE	ER OF RECORD:	DATE :

+

+

NOTES

REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN IN DRAWINGS ARE DEEMED NECESSARY BY ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE SUMMARY OF QUANTITIES TABLE.

FINAL JOINT SEALS SHALL NOT BE INSTALLED UNTIL THE SILANE DECK TREATMENT IS COMPLETE.

FOR ELASTOMERIC CONCRETE FOR PRESERVATION, SEE SPECIAL PROVISIONS.

FOR BRIDGE JOINT DEMOLITION, SEE SPECIAL PROVISIONS.

FOR SECTION A-A AND B-B, SEE JOINT REPAIR DETAILS SHEET S7-4.

SHOTBLASTING SILANE DECK CONCRETE DE BRIDGE JOINT

SUMMARY OF QUANTITIES FOR BARRIER RAIL TREATMENT

SURFACE PREP SILANE BARRIE

SUMMARY OF QUANTITIES FOR DECK AND APPROACH SLABS

	ESTIMATE	ACTUAL
IG BRIDGE DECK	1,104.1 SY	
TREATMENT	1,104.1 SY	
ECK REPAIR FOR SILANE DECK TREATMENT	0 SF	
DEMOLITION	228.4 SF	

	ESTIMATE	ACTUAL
PARATION FOR CONCRETE BARRIER RAIL	1,319.4 SF	
ER RAIL TREATMENT	1,319.4 SF	