

BRIDGE DATA

Map No.	Route No.	Route Name	Bridge No.	Posted SV	Posted TSS	Recommended Treatment, From Bridge Maintenance
7	3116	MILLS GAP ROAD	100173			DO NOT PAVE
8	3116	MILLS GAP ROAD	100471			COORDINATE WITH BRIDGE MAINTENANCE TO REMOVE EXISTING ASPHALT 15 DAYS BEFORE RESURFACING BEGINS.
10	3121	ROSE HILL ROAD	100794			DO NOT PAVE
12	3138	UPPER BRUSH CREEK ROAD	100090			COORDINATE WITH BRIDGE MAINTENANCE TO REMOVE EXISTING ASPHALT 15 DAYS BEFORE RESURFACING BEGINS.
13	3147	UPPER BRUSH CREEK ROAD	100089			COORDINATE WITH BRIDGE MAINTENANCE TO REMOVE EXISTING ASPHALT 15 DAYS BEFORE RESURFACING BEGINS.
23	3181	MILLER ROAD / LEE STREET	100172			DO NOT PAVE
34	3238	FAIRVIEW ROAD	100744			DO NOT PAVE
34	3238	FAIRVIEW ROAD	100059			DO NOT PAVE