



REQUIRED		
No.	DESCRIPTION	MARK
2	PLATE	P1
2	"	P2
6	"	P3
6	"	P4
2	"	P5
4	"	P6
2	"	P7
2	"	P8
2	BOTTOM LATERALS	BL1
10	"	BL2
6	"	BL3
1	"	BL4
2	ROLLER NEST	RN
2	ROLLER BED PLATE	BPI

GENERAL NOTES:
 MATERIAL: A.H. Structural Steel.
 SPECIFICATIONS: A.R.E.A. Current.
 HOLE: 1/8" diam. Unless Noted.
 SHOP INSPECTION: L. S. CRANE, Engineer of Tests,
 SOUTHERN RAILWAY COMPANY, ALEXANDRIA, VA.
 SHOP PAINT: One coat zinc chromate, Alkyd Vehicle,
 paint to Southern Railway Specification No. 128A,
 or equal. Formulation of Substitute paint to be
 approved by Railway Engineer of Tests prior to use.

MARK DATE BY REVISIONS

SOUTHERN RAILWAY SYSTEM
 RAILROAD DIVISION

OFFICE OF CHIEF ENGINEER, W. S. S. CHARLOTTE, N. C.

DETAIL OF (NEW) BOTTOM LATERAL SYSTEM AND REPAIR PARTS FOR N.B. TRACK ROCKY RIVER CROSSING

NO. 362.3 SCALE: 1/4" = 1'-0"
 DATE: March 21, 1914
 DRAWN BY: B. J. B. CHECKED BY: B. J. B. APPROVED BY: B. J. B.

Installed Dec 1913

ERECTION PLAN (ADD. BOTTOM LATERAL SYSTEM)