



SIDE VIEW NORTH FACE

ELEVATION WEST FACE





SIDE VIEW SOUTH FACE


ELEVATION EAST FACE


+



PROPOSED REPAIR AREAS

SUBSTRUCTURE SPALL/DELAMINATION





 DocuSigned by: Sanuel Cullum

RTH CAROLAN


FESSIO


SEAL 043571

GINE

PROJECT	NO	B-5937				
CURRIT	UCK.	/DAR	E_co	UNTY		
STATION:	BR	IDGE	NO.	16		

PROJECT	NO.	B-	5	<u>937</u>	,	
CURRIT	UCł	<td>RΕ</td> <td>CO</td> <td>UNI</td> <td>ΓY</td>	RΕ	CO	UNI	ΓY
STATION:	BF	RIDGE	Ν	10.	16	







SUBSTRUCTURE CONC. REPAIR - BENT 15

THELL CULTURE							
12/13/2016	REVISIONS				SHEET NO.		
DOCUMENT NOT CONSIDERED	NO.	BY:	DATE:	NO.	BY:	DATE:	S-34
FINAL UNLESS ALL	1			3			TOTAL SHEETS
SIGNATURES COMPLETED	2			4			