TOTAL BILL OF MATERIAL											
BRIDGE NO.	GROOVING BRIDGE FLOORS	CLASS II, SURFACE PREPARATION	FOAM JOINT SEALS	SYNTHETIC RUBBER EXPANSION JOINT SEAL	EXPANSION JOINT SEAL REPAIR	POLYESTER POLYMER CONCRETE MATERIALS	BRIDGE JOINT DEMOLITION	PLACING & FINISHING PPC OVERLAY	CONCRETE DECK REPAIR FOR PPC OVERLAY	SCARIFYING BRIDGE DECK	SHOTBLASTING BRIDGE DECK
	SQ.FT.	SQ. YDS.	LUMP SUM	LUMP SUM	LIN.FT.	CU. YDS.	SQ.FT.	SQ. YDS.	SQ. YDS.	SQ. YDS.	SQ. YDS.
143	92,379	29.5	LUMP SUM	_	105.5	381.3		10,934	29.5	10,934	10,934
159	151,252	9.1	LUMP SUM	LUMP SUM		613.7	449.2	17,585	9.1	17,585	17,585
TOTAL	243,631	38.6	LUMP SUM	LUMP SUM	105.5	995.0	449.2	28,519	38.6	28,519	28,519

+

.

+

DRAWN BY : \_\_\_\_\_ CHECKED BY : \_\_\_\_ J. YANNACCONE S. WANCE \_ DATE : <u>1/17</u> \_ DATE : <u>1/17</u>

29-JAN-2017 17:28 R:\Structures\FinalDrawings\I-5894\_SMU\_BM.dgn

