

REPAIR QUANTITY TABLE				
REPAIRS BENT 14	QUANTITIES ESTIMATE ACTUAL			
SHOTCRETE REPAIRS	AREA SF	VOLUME CF	AREA SF	VOLUME CF
CAP (VERTICAL FACE) CAP (HORIZONTAL, CORNER)	1.8 0.0	0.9		
EPOXY RESIN INJECTI	ON	LN. FT		LN.FT
САР		0.0		
VALUES IN CHART REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1"BEHIND REBAR AND MIN. 2"CL TO SAWCUT. SEE REPAIR DETAILS.				
- SHOTCRETE REPAIR				
ERI - EPOXY RESIN INJECTION				
La La				
END VIEW				
EAST SIDE				
END VIEW			B-5938	2
WEST SIDE PROJECT NO. <u>B-5938</u> <u>CARTERET</u> COUNTY				
			(( 68	
	<b>IDGE N</b> T 15 OF 5			
STATE OF NORTH CAROLINA				
DEPARTMENT OF TRANSPORTATION RALEIGH				
SEAL 21271				
BENT 14				
Docusigned by: Greg Dickey				
2/22/22/264698CE5B4B6		REVISIONS	1	SHEET NO.
DOCUMENT NOT CONSIDERED FINAL UNLESS ALL STONATURES COMPLETED	BY: D	ATE: NO. BY:	DATE:	S1-58 TOTAL SHEETS
SIGNATURES COMPLETED 🙎		4		