2 Phase Fully Actuated US 74 - Indian Trail CLS #1

1. Refer to "Roadway Standard Drawings NCDOT" dated January 2012 and "Standard Specifications for Roads and Structures" dated January 2012.

NOTES

- 2. Do not program signal for late night flashing operation unless otherwise directed by the Engineer.
- 3. Set all detector units to presence mode.
- 4. Locate new cabinet so as not to obstruct sight distance of vehicles turning right on red.
- 5. Install combination panel with pedestal extension (see Std drawing 1700.01).
- 6. The cabinet should be designed to include an Auxiliary Output file for future use.
- 7. Maximum times shown in timing chart are for free-run operation only. Coordinated signal system timing values supersede these values.

LEGEND

Traffic Signal Head

Modified Signal Head

Pedestrian Signal Head With Push Button & Sign

Signal Pole with Guy Signal Pole with Sidewalk Guy


PROPOSED

EXISTING

-

N/A

8. Closed loop system data: Controller Asset #2185.




PHASING DIAGRAM DETECTION LEGEND

---> PEDESTRIAN MOVEMENT

Ø6


PHASING DIAGRAM

DETECTED MOVEMENT UNDETECTED MOVEMENT (OVERLAP) UNSIGNALIZED MOVEMENT



SIGNAL FACE I.D.

All Heads L.E.D.




31,32 61,62 --L1- STA 126+20+/-86'+/- LT 55 mph 0% grade US 74 (Independence Boulevard) WB 55 mph -1.9% grade US 74 (Independence Boulevard) EB sidewalk

> __ -L1- STA 125+84 70'+/- RT

OASIS 2070	TIMING	CHART
	PHASE	
FEATURE	3	6
Min Green 1 *	7	14
Extension 1 *	2.0	6.0
Max Green 1 *	30	90
Yellow Clearance	3.0	5.2
Red Clearance	3.5	1.3
Red Revert	2.0	2.0
Walk 1 *	-	-
Don't Walk 1	-	-
Seconds Per Actuation *	-	1.5
Max Variable Initial *	-	46
Time Before Reduction *	-	15
Time To Reduce *	-	30
Minimum Gap	-	3.4
Recall Mode	-	MIN RECALL
Vehicle Call Memory	-	YELLOW
Dual Entry	-	-
Simultaneous Gap	ON	ON

* These values may be field adjusted. Do not adjust Min Green and Extension times for phase 6 lower than what is shown. Min Green for all other phases should not be lower than 4 seconds.



PLANS PREPARED BY: 5950 FAIRVIEW ROAD, SUITE 320

CHARLOTTE, NC 28210

NC LICENSE NO. C-2213 • (704) 332-2289

1"=40'

SR 1008 (Indian Trail Road)

Eastbound U-turn Division 10 Union County Indian Trail June 2015 REVIEWED BY: 750 N.Greenfield Pkwy,Garner,NC 27529 PREPARED BY: D. Ondieki REVIEWED BY: J. Beck

022516 Lisa M. Moon 8/30/2016

SIG. INVENTORY NO. 10-2185