



MATCHLINE-L- STA 161+00 (SHEET 15)

MATCHLINE-L- STA 174+00 (SHEET 17)

HANOVER DELEVELOPMENT CO.
MB 59 PG 311

148
HANOVER LAND, LLC
DB 4129 PG 437
DB 4123 PG 441
DB 4414 PG 403
DB 4476 PG 877
DB 4546 PG 380
DB 4736 PG 236
MB 8 PG 88

HANOVER LAND, LLC
DB 4129 PG 437
DB 4123 PG 441
DB 4414 PG 403
DB 4476 PG 877
DB 4546 PG 380
DB 4736 PG 236
MB 8 PG 88

149
ROMEO A. MISIERA
DB 858 PG 259
MB 8 PG 88

FOY S. THORNTON TRUST B, ET AL
DB 4924 PG 351
MB 8 PG 88
NOTE: DEED CONFLICTS WITH
ROMEO A. MISIERA
DB 858 PG 259

PAUL PRIDGEN, ET AL
DB 4408 PG 506
MB 8 PG 88

148
HANOVER LAND, LLC
DB 4129 PG 437
DB 4123 PG 441
DB 4414 PG 403
DB 4476 PG 877
DB 4546 PG 380
DB 4736 PG 236
MB 8 PG 88

SEE SHEET 2A-10 FOR U-TURN BULB-OUT DETAIL
SEE SHEET 41 FOR -L- PROFILE
SEE SHEET 2B-8 FOR CURVE DATA

7/14/2017
R:\V\2017\Proj\1601\Proj\1601\SH1\U4751.RD\RDY_psh16.dgn
C:\Users\jacob\OneDrive\Documents\1601\1601.dwg