


SECTION LOSS BEAM END REPAIR ("BE" REPAIR)

* REPAIR BEAM END REPLACEMENT PRIOR TO WEB PREPLACEMENT



FLANGE SUPPORT BRACKET

NOTE:

INSTALL FLANGE SUPPORT BRACKET PRIOR TO MAKING WEB PCUT REMOVE FLANGE SUPPORT BRACKET AFTER NEW WEB P HAS BEEN INSTALL. GRIND WELDS FLUSH PRIOR TO PAINTING. PROJECT NO. I-5889A BUNCOMBE COUNTY 374 BRIDGE NO.

SHEET 2 OF 2

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

> BEAM END REPAIR DETAILS

PLANS PREPARED BY: Gannett Fleming Excellence Delivered As Promised

	Ein Ball J 11/17/2017 BA9F91762D7044A
2610 Wycliff Road Suite 102	
Raleigh NC 27607-3073 (919) 420-7660	DOCUMENT NOT CONSIDERED FINAL UNLESS ALL
NC Lic. No. F-0270	SIGNATURES COMPLETED

SEAL 020208

		_					
		SHEET NO.					
FRFD	NO.	BY:	DATE:	NO.	BY:	DATE:	S-157
LIVLU	1			3			TOTAL SHEETS
ED	2			4			208

SECTION LOSS BEAM END REPAIR ("BE" REPAIR)

* REPAIR BEAM END REPLACEMENT PRIOR TO WEB P REPLACEMENT

★ WEB P REPLACEMENT

DATE: 10/2017 DATE: 10/2017 J.A. BOYER DRAWN BY : ___ R.NELSON CHECKED BY : _

* BEAM END REPLACMENT