
DocuSign Envelope ID: D8D6C137-29D6-4EF9-9111-4ED3C38	314F6

MT. HO	LICE ENCLOSURE AT CONNECTION ON OLLY-HUNTERSVILLE RD OF BROOKSHIRE BLVD.		
	SPLICE No. 6		
		EXISTING TRUNK CABLE MT. HOLLY–HUNTERSVI SOUTHBOUND TO ROZZELLES FERRY F	RD.
INCLUDE ON THE (COVER OF EACH SPLICE TRAY TH		
REFERENCE SECTION 1) SPLICE LOCATION 2) DATE 3) COMPANY NAM 4) NAME OF INDIV PRIOR TO INSTALLIN DIGITAL PHOTOGRAM	N 1731 "FIBER OPTIC SPLICE ENCL N	OSURE" G TRAY TAKE A AND INFORMATION	
COLOR CODE TIA/EIA 598–A (1) BLUE (7) RED (2) ORANGE (8) BLACK (3) GREEN (9) YELLOW (4) BROWN (10) VIOLET (5) SLATE (11) ROSE (6) WHITE (12) AQUA	THROU	ENTIRE BUFFER TUBE GH WITHOUT CUTTING LL FIBERS IN BUFFER	1. UNI SPL 2. UNI IN 3. ETH THI AN



NOTES

INUSED FIBER SHALL BE LEFT COILED AND STORED IN THE SPLICE TRAY.

JNUSED BUFFER TUBES SHALL BE LEFT COILED AND STORED IN THE SPLICE TRAY.

THERNET TERMINATION CONFIGURATIONS ARE GENERIC. THE CONTRACTOR SHALL BE RESPONSIBLE FOR DETERMINING AND ENSURING PROPER TERMINATION.



Stantec Consulting Services Inc. 801 Jones Franklin Road Suite 300 Raleigh, NC 27606 Tel. (919) 851-6866 Fax. (919) 851-7024 www.stantec.com License No. F-0672

Ν	CABLE TO SPLICE ENC MASTER SIGNAL CAB DLLY–HUNTERSVILLE RD DKSHIRE BLVD. (SPLICE	INFT AT					
FIE	BER BACKBONE CABLE						
SP	are conduit						
			TN	1P Ph	ase	e I	(Final)
	Prepared in the Offices of:	FIBER		SPLICE D CE No.6	ETAIL	_S	SEAL
	750 N. Greenfield Pkwy., Garner, NC 27529	DIV 10 PLAN DATE: PREPARED BY:		BURG CO. REVIEWED BY: REVIEWED BY:	CHARL D. HAR B. WAT	RIS	SEAL 29449
Ī	SCALE		VISIONS		INIT.	DATE	Betsy L. Watson 1/23/2018 35E67BB34E8743E SIGNATURE DATE
	N / A						CADD Filename:

PROJECT REFERENCE NO.

U-6084

SHEET NO.