



- Curb Ramp To Be Repaired
- Municipal Boundary
- NCHPO Historic Boundary (NR and LHD)

2021 West
WBS: 20201CPT.05.02.20921.1
SR 1652 from Beg Maint to NC 54

NORTH CAROLINA DEPARTMENT OF TRANSPORTATION
DIVISION 5

Source: CALYX Engineers and Consultants, ESRI, NC OneMap, NCDOT, NCHPO