



Curb Ramps To Be Repaired		
	Retrofit	
	Remove and Replace	
	New Curb Ramp	
	Remove Ramp	
	Municipal Boundary	
	NCHPO Historic Boundary (NR and LHD)	
2022 Durham		
WBS: 2021CPT.05.15.20321.1		
Goodwin Rd		
From US 501 To SR 1639		
	NORTH CAROLINA DEPARTMENT OF TRANSPORTATION DIVISION 5	
<small>Source: NV5 Engineers and Consultants Inc, ESRI, NC OneMap, NCDOT, NCHPO</small>		